

Forum discussion index

June 2000

- 1.1 Club Information - Welcome to Lake Amphibian Flyers Club Forum
- 2.1 General Discussion - Lake time line
- 3.1 Wing A.D. - Wing A.D. Comments Forum
- 4.1 General Discussion - Airventure 2000
- 5.1 Club Information - Looking for Don Seeley
- 6.1 General Discussion - Low water
- 7.1 General Discussion - New Lake owner and flight training
- 8.1 Wing A.D. - Wing A D
- 9.1 Parts & Repairs - Parts for sale, 200 prop needed
- 10.1 Parts & Repairs - Circuit breakers
- 11.1 Club Information - Auto gas
- 12.1 Does not exist
- 13.1 Does not exist
- 14.1 Fly-In Notices - Bahamas Oct 2000
- 15.1 Fly-In Notices - Sandpoint, Idaho fly-in September 8th
- 16.1 General Discussion - Skimmer serial #128, N270B
- 17.1 General Discussion - Skimmers
- 18.1 General Discussion - Change of nickname
- 19.1 Does not exist
- 20.1 Wing A.D. - Wing healer
- 21.1 Insurance - Lake Aircraft insurance
- 22.1 For Sale & Wanted Ads - Charts
- 23.1 Operating Techniques - Hand propping
- 24.1 General Discussion - Projects (La4-200 restoration, hydrofoil)
- 25.1 General Discussion - Would you be interested in hosting visiting Lake Flyers
- 26.1 For Sale & Wanted Ads - Lake parts (Prop for 180)
- 27.1 Fly-In Notices - Sandpoint Splash in cancellation
- 28.1 General Discussion - FAR big change
- 29.1 Wing A.D. - Alternate source for B-79 kit
- 30.1 Fly-In Notices - Should the annual convention be kept ...
- 31.1 Fly-In Notices - River Ranch alternative - help us find
- 32.1 General Discussion - Ramping a Lake on a mucky shore.
- 33.1 For Sale & Wanted Ads - Heater
- 34.1 Wing A.D. - B-79 Kit
- 35.1 General Discussion - Intercom
- 36.1 General Discussion - AV-Blend
- 37.1 Wing A.D. - Alternate source for B-79 Kit !
- 38.1 Fly-In Notices - "River Ranch" alternatives
- 39.1 Fly-In Notices - Ignore my last message!
- 40.1 Does not exist
- 41.1 General Discussion - EP on hoist (Pictures)

- 42.1 For Sale & Wanted Ads - LA 4 200 wanted**
- 43.1 Wing A.D. - Alternative wing AD kit announcement**
- 44.1 Does not exist
- 45.1 For Sale & Wanted Ads - 200 HP propeller**
- 46.1 General Discussion - Trim tabs**
- 47.1 For Sale & Wanted Ads - LA4-200 wanted**
- 48.1 General Discussion - Paint restoration & preservation**
- 49.1 Club Information - February 2001 Fly-in plan announcement**
- 50.1 For Sale & Wanted Ads - Sun N Fun merchandise special**
- 51.1 For Sale & Wanted Ads - Want Buccaneer, have Mooney**
- 52.1 Wing A.D. - Alternate source for B-79 Kit !**
- 53.1 For Sale & Wanted Ads - Private buyer seek best 200ep 9207380049**
- 54.1 Parts & Repairs - Aux. fuel tanks and plumbing**
- 55.1 Wing A.D. - Revo**
- 56.1 General Discussion - Depth finder For Lake ?**
- 57.1 General Discussion - Lake N333FM at Boeing Field, Seattle**
- 58.1 General Discussion - Places to visit in your Lake!**
- 59.1 Does not exist
- 60.1 For Sale & Wanted Ads - Water flying book**
- 61.1 For Sale & Wanted Ads - Go jump in a LAKE** (T-shirts)
- 62.1 Does not exist
- 63.1 General Discussion - Linear voltage regulators** (Master switch, relay)
- 64.1 Parts & Repairs - Door molding**
- 65.1 Parts & Repairs - Hull strakes** (Skidding turn)
- 66.1 Does not exist
- 67.1 Fly-In Notices - Recurrent training** (At fly-in)
- 68.1 Parts & Repairs - Vortex generators for Lakes** (Step taxi speed)
- 69.1 Does not exist
- 70.1 For Sale & Wanted Ads - For Sale** (Heater)
- 71.1 For Sale & Wanted Ads - For Sale 1963 LA4 180**
- 72.1 General Discussion - Dock for Skimmers and Lakes**
- Jan 2001**
- 73.1 For Sale & Wanted Ads - Factory Re-Man 200 HP IO-360-A1B Engine**
- 74.1 Operating Techniques - Mixture, manifold pressure and RPM**
- 75.1 For Sale & Wanted Ads - 200 HP Q-Tip prop for sale**
- 76.1 Parts & Repairs - Fuel bladder**
- 77.1 For Sale & Wanted Ads - Rare bird** (Lake Seaplane)
- 78.1 Insurance - And you thought Lakes had high insurance** (Robertson R22/44)
- 79.1 For Sale & Wanted Ads - 1975 la4-200 for sale**
- 80.1 Club Information - Newsletter, mailing problems**
- 81.1 Fly-In Notices - Notice to pilots flying to Winter Haven**
- 82.1 Wing A.D. - Correction re Canadian AD fix**
- 83.1 Fly-In Notices - Bahamas trip after Winter Haven**
- 84.1 General Discussion - Custom cover for engine**
- 85.1 Wing A.D. - Wing AD question** (Kit installation advice)

- 86.1 Does not exist
- 87.1 Operating Techniques - LA-4/180 - Excessive landing bounces?** (Step & glassy)
- 88.1 Wing A.D. - Comments on A. Revard mass E-Mail**
- 89.1 Wing A.D. - Wing ad pricing**
- 90.1 For Sale & Wanted Ads - LA 4 200 wanted**
- 91.1 Parts & Repairs - Nose strut problem**
- 92.1 Operating Techniques - Better cruise speed with new technique?**
(Aft CG, Elevator springs, ballast, Aircraft weight & CG)
- 93.1 Parts & Repairs - Aux fuel tanks** (Slow transfer, pumps, cabin heater)
- 94.1 Parts & Repairs - Need set nose doors**
- 95.1 Fly-In Notices - Arrival** (For Lakeathon)
- 96.1 Club Information - Important notice RE Forum posting**
- 97.1 Club Information - Photos of 2001 fly-in are available!**
- 98.1 For Sale & Wanted Ads - Partnership in Buccaneer available in CT**
- 99.1 General Discussion - Auto Pilot info/recommendations needed**
- 100.1 Club Information - How do you join the Lake Flyers Club?**
- 101.1 Club Information - Misc** (No newsletter)
- 102.1 Parts & Repairs - Restoration parts** (Needed)
- 103.1 General Discussion - Comments on lake flyers annual mtg**
- 104.1 Club Information - Attendance list from Winter Haven Fly-In**
- 105.1 Parts & Repairs - Wheel bearing grease**
- 106.1 General Discussion - Model of lake aircraft?**
- 107.1 General Discussion - Flying magazine**
- 108.1 Parts & Repairs - Breaking actuator rods** (Nose gear adjustment)
- 109.1 General Discussion - Camping-Lake Mead, Lake Powell**
- 110.1 General Discussion - Battery Charger** (Trickle/maintainer)
- 111.1 General Discussion - Outline sketch of Lake in e-file**
- 112.1 Operating Techniques - An emergency use for duct tape** (trim spring, Ramp climbing)
- 113.1 Club Information - Lake sharing or renting worldwide**
- 114.1 General Discussion - Lake sharing or renting worldwide**
- 115.1 For Sale & Wanted Ads - Opportunity in Fiji**
- 116.1 For Sale & Wanted Ads - Wanted - Heater**
- 117.1 Parts & Repairs - Need hydraulic pump, overhauled +8130**
- 118.1 Operating Techniques - Leaning** (TIT, EGT, CHT, timing)
- 119.1 Does not exist
- 120.1 Parts & Repairs - Bow ring** (Towing)
- 121.1 General Discussion - Turbo STC** (Converting LA4 to a -200)
- 122.1 Operating Techniques - Emergency stops** (Tight, sliding step-turn)
- 123.1 Wing A.D. - Wing AD patent**
- 124.1 General Discussion - Thanks!**
- 125.1 Wing A.D. - "Wolf"** (Wing AD patent)
- 126.1 Wing A.D. - "Press Release"** (Wing AD patent)
- 127.1 Wing A.D. - Off-Forum communication** (Wing AD patent)
- 128.1 Parts & Repairs - Tail ballast**
(Relocating battery, nose heavy, stall speed, CG location, control column springs)

- 129.1 For Sale & Wanted Ads - 200 HP Propeller for sale**
- 130.1 Wing A.D. - Once upon a time**
- 131.1 General Discussion - Interesting Links (Aeronautx.net and Archedyne vs Rivard)**
- 132.1 General Discussion - Email addresses for members?**
- 133.1 Fly-In Notices - Team up and Fly out**
- 134.1 Insurance - A good business model for Lake to note (Airsure insurance)**
- 135.1 Wing A.D. - Happy?**
- 136.1 Fly-In Notices - Otsego Lake splash-in**
- 137.1 Does not exist
- 138.1 For Sale & Wanted Ads - Free Loran antenna**
- 139.1 General Discussion - Boat church**
- 140.1 Does not exist
- 141.1 Wing A.D. - Renegade wings on Buccaneer**
- 142.1 Parts & Repairs - Hydraulic fluid specs**
- 143.1 Club Information - Member list - E-Mail addresses**
- 144.1 Club Information - Family Lake trips and Paris lo**

June 2001

- 145.1 Operating Techniques - Wing float buoyancy**
- 146.1 General Discussion - Air oil separator**
- 147.1 Fly-In Notices - Otsego Lake Splash-In is this week 6/8**
- 148.1 Does not exist
- 149.1 Parts & Repairs - Air/oil separator (Renegade)**
- 150.1 Fly-In Notices - Great destinations**
- 151.1 Parts & Repairs - Micro AeroDynamics VG's for Lake (Alternator/regulator, Scat hose)**
- 152.1 For Sale & Wanted Ads - 1978 LA-4-200 For Sale**
- 153.1 Does not exist
- 154.1 Parts & Repairs - Air box intake mod.**
- 155.1 Operating Techniques - Vortex generators, do they really work?**
- 156.1 Fly-In Notices - Lakes to Oshkosh**
- 157.1 Club Information - Nice web sites**
- 158.1 Club Information - Hopes/prayers For Tom & Marilyn Pletcher**
- 159.1 Does not exist
- 160.1 General Discussion - Causley speed mods**
- 161.1 Operating Techniques - How do I keep from getting stuck? (Ramp materials)**
- 162.1 General Discussion - Tom and Marilyn Pletcher report**
- 163.1 Parts & Repairs - Vortex generators**
- 164.1 For Sale & Wanted Ads - 1959 C-2 Colonial Skimmer**
- 165.1 For Sale & Wanted Ads - Lake LA4-200 SN 806**
- 166.1 General Discussion - Update on Tom & Marilyn Pletcher**
- 167.1 General Discussion - Paint?**
- 168.1 General Discussion - Volunteers wanted !**
- 169.1 General Discussion - Yes, we would be interested in hosting visiting Lake Flyers**
- 170.1 Fly-In Notices - 2002 annual fly in**
- 171.1 Parts & Repairs - Flat tire? (Wheel jack)**
- 172.1 For Sale & Wanted Ads - Covers...**

- 173.1 General Discussion - Killarney Lake Safety Fly-in
- 174.1 Parts & Repairs - Concord 35XC battery (AGM, Recombinant)
- 175.1 Operating Techniques - Tire pressure
- 176.1 Parts & Repairs - SLA Batteries
- 177.1 General Discussion - 6213V flies again! (Paint, Garmin 430 / 530)
- 178.1 General Discussion - Drag of heater
- 179.1 Parts & Repairs - Electronic tachometer
- 180.1 Insurance - \$6214.00 premium
- 181.1 Fly-In Notices - Basin Harbor for lunch
- 182.1 Operating Techniques - Water operations (Cocked nose wheel, Neutral trim / step)
- 183.1 Club Information - Alternator (Failure - came apart)
- 184.1 General Discussion - Need a helping hand
- 185.1 Does not exist
- 186.1 General Discussion - World Trade Center
- 187.1 For Sale & Wanted Ads - 1976 Buccaneer for sale
- 188.1 General Discussion - Seaplane area (IFR operation)
- 189.1 General Discussion - Lake aircraft models
- 190.1 Fly-In Notices - Sept 29 Fla. Fly-In
- 191.1 Parts & Repairs - Great price on Lord mounts
- 192.1 For Sale & Wanted Ads - Fuel tanks for sale (Alternator, Regulator)
- 193.1 Operating Techniques - Prop limits (Step taxi, Reduced RPM)
- 194.1 Parts & Repairs - Alternator approval (Regulator, Wiring)
- 195.1 Operating Techniques - Yoke tension (Trim)
- 196.1 Operating Techniques - Renegade turbo survey (Power settings, Fuel flow, IAS, Gami)
- 197.1 Operating Techniques - Lake to land on skis (Bradway stories, Spin)
- 198.1 Parts & Repairs - Hatch holder-openers
- 199.1 Operating Techniques - Mooring tips
- 200.1 General Discussion - Photo of 1960 LA-4 on skis
- 201.1 General Discussion - Hard starting (Impulse coupling, Relay, Idle cutoff leak)
- 202.1 Fly-In Notices - South Florida seaplane lunch planned
- 203.1 For Sale & Wanted Ads - Lake for sale
- 204.1 General Discussion - SPA forum
- 205.1 General Discussion - Mags (Dual impulse couplings legal?)
- 206.1 General Discussion - Slick (Dual impulse couplings legal)
- 207.1 Does not exist
- 208.1 Club Information - Harry Shannon
- 209.1 General Discussion - Tow bars
- 210.1 Fly-In Notices - A place to visit mid November 01
- 211.1 Club Information - Annual Safety Seminar Fly-in announcement
- 212.1 Parts & Repairs - Beacons (Wire leads breaking)
- 213.1 Club Information - Club email & fax problems
- 214.1 Does not exist
- 215.1 General Discussion - Gear legs
- 216.1 Parts & Repairs - Push to talk switch problem
- 217.1 Does not exist

- 218.1 For Sale & Wanted Ads - SW FL home with ramp for Lake
- 219.1 Parts & Repairs - Fuel float RH (For sale)
- 220.1 For Sale & Wanted Ads - Colonial C-2
- 221.1 Club Information - Instruction available @ Annual Fly-In
- 222.1 For Sale & Wanted Ads - "Go Jump in a Lake" sweats and T-shirts
- 223.1 General Discussion - Carb heat
- 224.1 Parts & Repairs - Gear actuator (Looking for one)
- 225.1 For Sale & Wanted Ads - Incredible deal on IO-360-A1B6 Engine
- 226.1 For Sale & Wanted Ads - Wanted - Rajay turbo for LA-4-200
- 227.1 General Discussion - Balance of plane
- 228.1 General Discussion - Hull and rivets (Ballast, Balance, Sealant)
- 229.1 General Discussion - Concorde RG35 battery (Hold-down bracket)
- 230.1 General Discussion - Engine change (SMA diesel, Superior IO380)
- 231.1 For Sale & Wanted Ads - Nice LA4-200
- 232.1 Parts & Repairs - Hydraulic accumulator
- 233.1 Parts & Repairs - Prop AD ?
- 234.1 Club Information - Recurrent training at convention
- 235.1 General Discussion - GAMIS (Turbo check-out and operation)
- 236.1 Parts & Repairs - Doors popping open
- 237.1 Operating Techniques - VGs on renegade- an update (Glassy water)
- 238.1 General Discussion - Feeling OK?
- 239.1 General Discussion - Aeroshell oil recall
- 240.1 Operating Techniques - Lake owners manual for sale on ebay
- 241.1 Fly-In Notices - Formation flying clinic in February
- 242.1 General Discussion - Wing fairings
- 243.1 Does not exist
- 244.1 Parts & Repairs - Sticky water rudder
- 245.1 General Discussion -Initial instruction - and heaters
- 246.1 Parts & Repairs - Nose gear screw-up. (Piston, plug, socket)
- 247.1 Fly-In Notices - Monthly Florida fly-ins
- 248.1 Club Information - Airport shut down
- 249.1 Does not exist
- 250.1 Does not exist
- 251.1 Operating Techniques - Hydrofoil on Lake
- 252.1 General Discussion - Seafire TA 16
- 253.1 Operating Techniques - Thanks Paul Furnee
- 254.1 Operating Techniques - Thanks to Paul
- 255.1 General Discussion - LASAR ignition system & Lakes
- 256.1 General Discussion - Osama & fishing
- 257.1 Does not exist
- 258.1 General Discussion - Camera port in canopy? (Hatch open inflight, Modifications)
- 259.1 For Sale & Wanted Ads - LA4-200 for sale
- 260.1 Parts & Repairs - Minor parts and repair (Throttle handle, air scoops, snap vents)
- 261.1 General Discussion - Gerdes brakes
- 262.1 Operating Techniques - How cold is "cold"...? (Starting, preheat)

Jan 2002

- 263.1 General Discussion - Logos & clothing**
- 264.1 General Discussion - Convention car rental information**
- 265.1 General Discussion - Our future licenses**
- 266.1 Operating Techniques - Photo sequence gear down water landing**
- 267.1 Club Information - Phone** (Copeland)
- 268.1 For Sale & Wanted Ads - Help prospective new owner** (Prebuy inspection, Maintenance costs)
- 269.1 Parts & Repairs - Janitrol heater for sale, fresh annual**
- 270.1 General Discussion - Winter Haven Fly-in**
- 271.1 Club Information - Lake flight jacket patch**
- 272.1 Fly-In Notices - Convention**
- 273.1 Does not exist
- 274.1 General Discussion - EP** (Straight vs turbo-ed)
- 275.1 Fly-In Notices - 2002 Convention program**
- 276.1 General Discussion - Wish list**
(Auto pilot, Tanis heater Engine monitor, VG's, Strikefinder, Electric elevator trim)
- 277.1 Parts & Repairs - Battery location**
- 278.1 For Sale & Wanted Ads - LA4-200 For Sale**
- 279.1 Parts & Repairs - Door seal**
- 280.1 Club Information - Lake Fly-In**
- 281.1 Parts & Repairs - Grease**
- 282.1 General Discussion - Tan Tara seaplane base**
- 283.1 Parts & Repairs - Gear up** (Accumulator charge, Retraction time)
- 284.1 General Discussion - Comments on Lakeflyer annual seminar**
- 285.1 Wing A.D. - New marketing technique... Sue your customers** (Wing AD patent)
- 286.1 Operating Techniques - Beach launcher**
- 287.1 General Discussion - Bahama's via Lake**
- 288.1 Operating Techniques - Slipping techniques**
- 289.1 Wing A.D. - Engine developments** (SMA diesel)
- 290.1 Insurance - Insurance question**
- 291.1 For Sale & Wanted Ads - 1978 LA-4-200**
- 292.1 General Discussion - Buying a Lake - weight questions** (Mods, Accessories, 430, MX-20)
- 293.1 Operating Techniques - Cross wind landings**
- 294.1 For Sale & Wanted Ads - 1981 Lake LA4-200 for sale**
- 295.1 Parts & Repairs - Mechanical fuel pump**
- 296.1 General Discussion - Renegade recovery**
- 297.1 For Sale & Wanted Ads - Seawind, would like Buccaneer in trade**
- 298.1 General Discussion - Warning to all prospective buyers**
- 299.1 Insurance - SPA and Falcon Insurance Agency team up**
- 300.1 General Discussion - Fly-in to Lake Powell**
- 301.1 Wing A.D. - Prior art**
- 302.1 Parts & Repairs - Aft compartment bilge**
- 303.1 Does not exist
- 304.1 Does not exist
- 305.1 Insurance - What does out policy cover?**

- 306.1 For Sale & Wanted Ads - Lake for sale on Ebay**
- 307.1 General Discussion - Electrical "chirp"** (Alternator, Regulator, Connections)
- 308.1 Parts & Repairs - Gerdes brake pad replacement part No.**
- 309.1 General Discussion - General discussion** (Lake flying)
- 310.1 Fly-In Notices - April 10 at Lekarica - Lake Easy**
- 311.1 General Discussion - Commercial SEL in a Lake Renegade**
- 312.1 Parts & Repairs - Fuel cell** (Bladder hangers, Snaps)
- 313.1 Parts & Repairs - Basic electrical questions - clock and EGT**
(Gear & flap handles, Drooping, creeping trim,)
- 314.1 Operating Techniques - Trolling motors** (Fishing)
- 315.1 Wing A.D. - Aero-News Network piece on wing AD**
- 316.1 Wing A.D. - Engine STCs** (Pre-oiler)
- 317.1 Parts & Repairs - Sheet metal cracks and stop-drilling** (Aft pylon fairing)
- 318.1 General Discussion - Ham Radio questions**
- 319.1 Does not exist
- 320.1 Parts & Repairs - Help! Landing gear trouble !** (Trailing-beam pivot tube free-play)
- 321.1 General Discussion - How much does a Lake weigh?** (Gear doors, Jacking one wing)
- 322.1 For Sale & Wanted Ads - 1977 Lake LA4-200 For sale**
- 323.1 General Discussion -The value of this forum** (Old Lake pictures, Balance, CG)
- 324.1 For Sale & Wanted Ads - Turbo Lake for sale**
- 325.1 Parts & Repairs - Conversion of heater inlet to fresh air?** (Air scoop, Evacuation vents)
- 326.1 Does not exist
- 327.1 General Discussion - Website**
- 328.1 Insurance - Under-insuring your aircraft**
- 329.1 Operating Techniques - Lake training** (High altitude, Mixture, Performance)
- 330.1 General Discussion - Need little help voltage regulator** (Shock mounts, Circuit breakers)
- 331.1 General Discussion - Buc or EP?**
- 332.1 Fly-In Notices - Otsego Lake Splash-In 2002**
- 333.1 For Sale & Wanted Ads - 1976 Buccaneer for sale with new engine!**
- 334.1 Operating Techniques - Hot running Lake** (CHT)
- 335.1 General Discussion - Shoulder harness for older 180**
- 336.1 General Discussion - Lake on air cushion**
- 337.1 General Discussion - Covers for landing gear switches**
- 338.1 General Discussion - Trying to find member**
- 339.1 General Discussion - Lake on hydrofoil**
- 340.1 Parts & Repairs - Parts & Repairs** (Dynamic propeller balancing)
- 341.1 Fly-In Notices - Details of Lake Powell fly-in**
- 342.1 Parts & Repairs - EGT** (Probes)
- 343.1 Operating Techniques - Jump start?** (Spare battery, Booster pack, Solar panel)
- 344.1 Parts & Repairs - Oil filter inspections**
- 345.1 Operating Techniques - Water in aux Tank**
- 346.1 Parts & Repairs - Looking for 85 EP spinner**
- 347.1 Parts & Repairs - Help, fuel flow problem !** (Pump overhaul, Filter, Boost pump)
- 348.1 Operating Techniques - Anchors**
- 349.1 Parts & Repairs - Have Renegade, need advice...** (Cylinders)

350.1 For Sale & Wanted Ads - 1970 LA4-200 for sale in Chattanooga, TN

351.1 Operating Techniques - Checklist

352.1 Parts & Repairs - Looking for a spinner P/N D-4824-L

353.1 General Discussion - Got a screw loose?

354.1 Does not exist

June 2002

355.1 Wing A.D. - Rivard prices

356.1 For Sale & Wanted Ads - 1985 EP with Renegade wings

357.1 Does not exist

358.1 General Discussion - Annoying banner

359.1 General Discussion - Nose gear problem (Shimmy)

360.1 Parts & Repairs - Gear retraction without jacks??

361.1 Parts & Repairs - Old hydraulic pumps

362.1 Parts & Repairs - Yoke centering spring brackets failure

363.1 Parts & Repairs - Yoke control springs

364.1 General Discussion - River Ranch reopens in July!

365.1 General Discussion - Rivard/Gioia trial (Wing AD)

366.1 Parts & Repairs - Idle problem (Throttle cable, Plug fouling)

367.1 For Sale & Wanted Ads - Update: 77 LA4-200 For sale price reduced

368.1 Parts & Repairs - Vapor lock in LA 4-200 (Fuel filter)

369.1 Parts & Repairs - Electric trim

370.1 Parts & Repairs - Electrical failure (Ground connection, Fuel filter)

371.1 Club Information - Hard to sign on

372.1 General Discussion - Hotels that support seaplanes

373.1 Parts & Repairs - Engine monitors

374.1 General Discussion - Who is he? (Broker)

375.1 Operating Techniques - Normal oil temperature at high OAT

376.1 Parts & Repairs - Heater related question

377.1 Wing A.D. - Furnee Lake Flyer article

378.1 Parts & Repairs - Effect of intake air scoop

379.1 Parts & Repairs - New aileron noise

380.1 General Discussion - Vortex generators- one year's experience

(Lost VG's, 180 performance, Water operation)

381.1 Parts & Repairs - 110 degrees.....! (Cabin heater)

382.1 General Discussion - Outboard

383.1 Does not exist

384.1 Fly-In Notices - Blast off to Oshkosh

385.1 Parts & Repairs - - Hydraulic leak (Pin hole, Restrictor, Oil line, Fuel line)

386.1 Parts & Repairs - Water rudder (Handle over-center, Steel cable guide)

387.1 Club Information - Lake model kit on Ebay- radio controlled

388.1 Parts & Repairs - Oil leaks (Separator, Breather, Blow-by, Capacity)

389.1 Parts & Repairs - Antenna base mount gasket

390.1 Operating Techniques - Lake accidents (Links, Checklist, Fuel, Filter,

Vapor lock, Recurrent training, Oil, Cold, Frost, Aux pump, Flaps, Batwings,

T270 starts, Hand prop, gear-down water, Spins, Stalls, VG's, Engine failure, Hung gear)

- 391.1 Does not exist
- 392.1 Fly-In Notices - Ontario**
- 393.1 Parts & Repairs - Hydraulic oil leak** (Brakes, Actuators)
- 394.1 Parts & Repairs - Jacking**
- 395.1 Parts & Repairs - Fuel Leak** (Old fuel hose)
- 396.1 General Discussion - Oshkosh**
- 397.1 Operating Techniques - Take off distance**
- 398.1 Parts & Repairs - Help** (Digital OAT gauge)
- 399.1 Parts & Repairs - Help...! Wheel bearings....?** (Fuel filter, Peanuts,)
- 400.1 Parts & Repairs - More on fuel filters and vapor lock**
- 401.1 Parts & Repairs - Alternator question**
- 402.1 Parts & Repairs - Main gear axle "lock" nuts...and grease** (Foam)
- 403.1 Fly-In Notices - Clear Lake, Calif meet... ??**
- 404.1 Parts & Repairs - Brake leak** (Bleeding)
- 405.1 Parts & Repairs - Voltage regulator** (Alternator, Wiring)
- 406.1 Parts & Repairs - Buccaneer up and down lock switches?**
- 407.1 For Sale & Wanted Ads - Turbo Lake 270 to be auctioned Aug 28**
- 408.1 General Discussion - Flying to Turks and Caicos**
- 409.1 Insurance - Try this** (Canadian requirements/limits, Links)
- 410.1 Parts & Repairs - Voltage regulator mounting**
- 411.1 Parts & Repairs - 1973 Lake item for auction on Ebay**
- 412.1 General Discussion - Ground Zero overflight**
- 413.1 Parts & Repairs - Sponson gas tanks** ('Wet' floats, JPI fuel flow, Transducer)
- 414.1 Operating Techniques - Hand propping a lake**
- 415.1 Does not exist
- 416.1 Wing A.D. - New wing crack alert & possible new AD** (Patent review)
- 417.1 General Discussion - HF Radio installation**
- 418.1 Parts & Repairs - Propeller Grease** (Link)
- 419.1 Parts & Repairs - Magneto Capacitors**
- 420.1 Does not exist
- 421.1 Parts & Repairs - Paint shops for Lakes**
- 422.1 For Sale & Wanted Ads - 1980 LA 4 200 for sale**
- 423.1 Does not exist
- 424.1 Wing A.D. - New Wing AD** (Continues 416)
- 425.1 Does not exist
- 426.1 General Discussion - Structural differences between 180 & 200**
- 427.1 Parts & Repairs - Fuel supply hose proximity to exhaust** (IO-390)
- 428.1 Wing A.D. - Crack** (Continues 416)
- 429.1 Operating Techniques - Securing a Lake on a floating dock**
- 430.1 Club Information - Florida lakefront home for sale**
- 431.1 Parts & Repairs - For sale** (Parts at Barnstormers)
- 432.1 General Discussion - Lake shares program**
- 433.1 Does not exist
- 434.1 Wing A.D. - Patent review**
- 435.1 Club Information - Newsletter mailing problem**

- 436.1 General Discussion - Why fly a Lake
- 437.1 General Discussion - Autopilots
- 438.1 General Discussion - Web site links (Members)
- 439.1 For Sale & Wanted Ads - Sponson for 180 la4
- 440.1 General Discussion - Lake as a camper
- 441.1 Fly-In Notices - Bahama fly-in
- 442.1 Parts & Repairs - Fuel dip stick
- 443.1 Does not exist
- 444.1 Operating Techniques - Folding fuel dip stick
- 445.1 General Discussion - Site question
- 446.1 General Discussion - New prop For LA 4 -with reverse! (MT, composite)
- 447.1 General Discussion - Vortex Generators - A misnomer?
- 448.1 General Discussion - Sale of Aerofab (Wadi Rahim, Promotional video, Gioia judgement)
- 449.1 Operating Techniques - Climb rates (Performance, Takeoff distance, -200 prop on a 180, No-floats, Rigging, Mods, Density altitude, Engine alignment, video camera,)
- 450.1 General Discussion - The greatest event for Lake (Sale of Lake ?)
- 451.1 Parts & Repairs - Help! Need service parts (Serrated washer, O-rings, U-joints)
- 452.1 General Discussion - Looking for a club member
- 453 General Discussion - For fun
- 454.1 Operating Techniques - Trim topics (2800 RPM)
- 455.1 Operating Techniques - Lost article
- 456.1 Wing A.D. - New AD issued (Follow-up wing AD, see 416)
- 457.1 Parts & Repairs - Gear up landings
- 458.1 Club Information - Getting to know more about one another
- 459.1 General Discussion - Water brakes (MT reversing propeller)
- 460.1 General Discussion - Turbo Renegade AD
- 461.1 Operating Techniques - Propeller aiming
- 462.1 Does not exist
- 463.1 General Discussion - Video camera mount
- 464.1 General Discussion - Coast Guard Auxiliary
- 465.1 Does not exist
- 466.1 For Sale & Wanted Ads - Wanted IO 360 A1B6
- 467.1 General Discussion - EP value
- 468.1 Parts & Repairs - Intake air scoops
- 469.1 Parts & Repairs - Factory bolt price
- 470.1 Parts & Repairs - Transponder (Antenna)
- 471.1 Parts & Repairs - How much are floats worth ?
- 472.1 General Discussion - Lake ferry pilots (Heater in nose)
- 473.1 General Discussion - Warning! before dealing with new owner
- 474.1 General Discussion - Interesting Links (NOAA Lake flying)
- 475.1 Parts & Repairs - De-greasing wheel wells, etc.
- 476.1 Parts & Repairs - Fuel injectors (Lean of peak)
- 477.1 General Discussion - Cost of annual (Inspection)
- 478.1 Insurance - Latest
- 479.1 General Discussion - Baker Lake and the Kazan watershed

- 480.1 Parts & Repairs - I just lost a hull plug
- 481.1 Parts & Repairs - Hull drainage
- 482.1 Parts & Repairs - Heater for La4-200 (Electric car seats & clothes, Exhaust muff)
- 483.1 Insurance - Brokers and forced agency
- 484.1 Parts & Repairs - Performance tinkering (Timing, CG, Weight, Power settings, Wing root fairings, RPM, VG's, Trim, Loop, Porpoise, Moving battery & hydraulic pump, 'Monty Barrett' overhaul, Gamis,)
- 485.1 General Discussion - Wingtips (Causley, Copeland)
- 486.1 Operating Techniques - Top tips not in the book or elsewhere (Crosswind, Night water, Step taxi/waterspeed, Mud stuck, Oil change, Kneeling)
- 487.1 Parts & Repairs - Aileron clicks (Yoke, U-joint)
- 488.1 Parts & Repairs - Hydraulic accumulator pressure (Location, Charge procedure)
- 489.1 Fly-In Notices - Bahama annual fly-ins
- 490.1 General Discussion - Federal Terrorist Insurance law
- 491.1 Parts & Repairs - What I carry with me in the aircraft (Gloozit, VG's)
- 492.1 Parts & Repairs - Excessive engine smoke (Turbo, Operation, MP, RPM, Detonation, Piston failure, Idle mixture adjustment, Auto gas, Fuel filter, Vapor lock,)
- 493.1 Operating Techniques - Pre-Heating (Multi-grade oil,)
- 494.1 General Discussion - Loss of Seawind
- 495.1 General Discussion - Canadian camping and fishing
- 496.1 General Discussion - Anywhere Pilot GPS (Garmin 295, Links)
- 497.1 Operating Techniques - Accompanied flight (Coordination with GPS)
- 498.1 Club Information - Article on back from oblivion
- 499.1 Parts & Repairs - Lakes fly lousy (Control yoke springs)
- 500.1 Parts & Repairs - Barnstormers (Skimmer remains in Quebec)
- 501.1 Parts & Repairs - Airspeed (Errors, Pitot-static)
- 502.1 Parts & Repairs - Radio transmission noise
- 503.1 General Discussion - AD (Wing)
- 504.1 For Sale & Wanted Ads - Renegade yokes
- 505.1 Fly-In Notices - Going to the convention from the West?
- 506.1 General Discussion - West Coast pre-purchase Inspection
- 507.1 Parts & Repairs - Crummy-air-oil separators (Condensation, Crankcase vent, Vent tube slit)
- 508.1 Does not exist
- 509.1 General Discussion - Schools with Lakes
- 510.1 Parts & Repairs - What's in your toolbox?
- 511.1 Parts & Repairs - Need right elevator
- 512.1 Parts & Repairs - I need the wing AD (Links)
- 513.1 Parts & Repairs - FAA required inspections

Jan 2003

- 514.1 Operating Techniques - Lake glide ratio (Prop pitch, Engine failure, Windmilling, Shut down)
- 515.1 Operating Techniques - Using GPS to get TAS (Calculators, Density Altitude, E6B)
- 516.1 General Discussion - For fun
- 517.1 Parts & Repairs - Struts question (Oleo servicing, PC virus, Schrader valve, Granville strut seal)
- 518.1 Parts & Repairs - Mag drop (Harness, condenser, points, gap)
- 519.1 Fly-In Notices - Montana splash in

- 520.1 **Operating Techniques - Emergencies** (Handling, AOPA article, Checklist)
- 521.1 **Club Information - Photos of central florida fly-in Jan 5 03** (Link)
- 522.1 **Parts & Repairs - Brake disks for Gerdes wheels** (Shoulder harness, Clevelands, Seals)
- 523.1 **Club Information - Airsure 2003 quotes**
- 524.1 **General Discussion - Propeller AD**
- 525.1 **Parts & Repairs - LA-4 180 Propeller** (-200 prop, Q-tip, Performance)
- 526.1 **Club Information - Lake Buc R/C flying model kit on Ebay**
- 527.1 **General Discussion - A presentation of a new Italian member** (Book, 'Seaplane Operations')
- 528.1 **Club Information - Owner profile**
- 529.1 **For Sale & Wanted Ads - 1986 Piper Malibu for**
- 530.1 **Fly-In Notices - Free ride offer to Winter Haven Fly-In**
- 531.1 **Operating Techniques - High MP/ Low RPM Operation** (Restrictions, Limitations, Efficiency)
- 532.1 **Operating Techniques - Off airport operations** (Link)
- 533.1 **Operating Techniques - Danger - reminder** (Towers)
- 534.1 **General Discussion - Forward-reverse in water**
- 535.1 **Fly-In Notices - Winter Haven Progress**
- 536.1 **Parts & Repairs - Engine overhaul**
- 537.1 **Parts & Repairs - Drawings for sponson conversion**
- 538.1 **Club Information - 2003 Lake flyers meeting**
- 539.1 **General Discussion - Oil Changes** (100 plus, Camshaft, Lobe wear, oil level)
- 540.1 **Club Information - Member list**
- 541.1 **General Discussion - 2003 Convention.**
- 542.1 **General Discussion - Accident on Lake Weir** (Jack Gilson, Renegade, NTSB link, glassy)
- 543.1 **Operating Techniques - Reversing prop**
- 544.1 **General Discussion - Lake factory to move?**
- 545.1 **Parts & Repairs - LA4-180 200HP conversion**
(STC, Performance, Water technique, High density altitude, Trim, Forward CG)
- 546.1 **Operating Techniques - Engine timing** (Type certificate, Performance test, External power plug, Impulse coupling, Gerdes mag switch, Starter kick-back)
- 547.1 **General Discussion - Accident on Lake Weir** (Glassy, Swells,)
- 548.1 **Parts & Repairs - Need right elevator**
- 549.1 **Parts & Repairs - Jacks for LA4-200**
- 550 **For Sale & Wanted Ads - Partner or archangel needed**
- 551.1 **General Discussion - Annual inspections** (Cost, Lake specialty shops)
- 552.1 **Operating Techniques - Adverse yaw** (Crosswind, Step turns)
- 553.1 **Parts & Repairs - No charging by the alternator**
(Regulator, Tests, Over-voltage, Adjustment, Master relay, Highspeed starter)
- 554.1 **Operating Techniques - Glassy water technique** (Bounce, Stall landings, VG's, Rough water)
- 555.1 **General Discussion - Super LA-4!**
- 556.1 **For Sale & Wanted Ads - Q-tip prop for sale**
- 557.1 **For Sale & Wanted Ads - IO-360A1B6, Still looking.** (Turbo Buc Performance numbers)
- 558.1 **General Discussion - The Russians are coming** (Beriev Be-103 amphibian)
- 559.1 Does not exist
- 560.1 **Club Information - Winter Haven Lake Fly-in Videos?**
- 561.1 **Operating Techniques - Securing plane** (Hydraulic, Bleed, Reservoir level,, Hand pump,)

- 562.1 General Discussion - Glassy water technique (Night, Landing light,)
- 563.1 For Sale & Wanted Ads - Half-price parts & supplies (Sold)
- 564.1 Operating Techniques - Operational Techniques
- 565.1 General Discussion - Cross countries (Routes)
- 566.1 Parts & Repairs - GPS antenna
- 567.1 Parts & R - Aux tank
- 569.1 Club Information - Parts catalogue on Ebay LA 4
- 570.1 General Discussion - ATP/CFII -40hrs in lakes
- 571.1 Parts & Repairs - Seat belts (Airframe, Impact, Failure)
- 572.1 Does not exist
- 573.1 Operating Techniques - Hydraulic failure in flight (Hand pump, preflight)
- 574.1 General Discussion - Lake clothing
- 575.1 Parts & Repairs - Seat belts
- 576.1 Club Information - Photo contest and a cool Lake. (Link to 'Super Lake' photo)
- 577.1 General Discussion - Water flying magazine
- 578.1 General Discussion - Either or (Flying destination)
- 579.1 Parts & Repairs - Vertical card compass
- 580.1 Fly-In Notices - West Coast Fly-Ins
- 581.1 Operating Techniques - Props (Three blade)
- 582.1 For Sale & Wanted Ads - 250 Renegade for sale
- 583.1 Parts & Repairs - Corrosion X vs. ACF-50 (BoeShield, Rejex)
- 584.1 General Discussion - Fish/Depth Finders (Trolling motor)
- 585.1 Operating Techniques - Ideas for improvements (Starter, Annunciator, Traffic, pressure switch, Digital tach. CD player, Aux plug, Fuel flow, Relays, Pump, Vacuum, Garmin 430, Jump start, Stormscope, Aux/boost pump, Jet pump, Vaporization,)
- 586.1 General Discussion - Aviation life vests (Accident survivability study) (Egress)
- 587.1 Fly-In Notices - Oshkosh 2003 (Camping)
- 588.1 Fly-In Notices - Otsego Lake Splash-In June 13,14,15
- 589.1 Operating Techniques - VHF antenna on top?
- 590.1 General Discussion - Lake 180HP pure seaplane
- 591.1 Fly-In Notices - Yellowknife Fly-In
- 592.1 Fly-In Notices - Boycott Speculator!
- 593.1 General Discussion - Foam in nose? (Floatation, Insulation, Ping pong, Alarm, Door handles)
- 594.1 Parts & Repairs - Propeller balancing
- 595.1 General Discussion - Grand Champion Seaplane
- 596.1 General Discussion - Flying to Cancun
- 597.1 Operating Techniques - In-cockpit check list (Procedure, training, instruction)
- 598.1 Operating Techniques - Mode S transponder (GTX 330, Anti collision, TIS, TCAS)
- 599.1 Club Information - Lake Flyer newsletter (Model kit)
- 600.1 Parts & Repairs - Door/hatch handle locks (Cover)
- 601.1 Does not exist
- 602.1 Does not exist
- 603.1 Parts & Repairs - Caulking keel (Sealants, 5200, Bostik 912, Proseal, 1422, Gas cap)
- 604.1 Operating Techniques - Towing a Lake backwards is a NO-NO
- 605.1 For Sale & Wanted Ads - Renegade yokes

- 606.1 General Discussion - Kits (Models)
- 607.1 Parts & Repairs - Factory hoses (Leak)
- 608.1 Parts & Repairs - Strut service question (Strut pressure, Nitrogen, T valve,)
- 609.1 Parts & Repairs - Foolproof hull leak detection method (Ultrasonic)
- 610.1 General Discussion - Cradle for hull (Ramp)
- 611.1 Club Information - This web site (Few members are using it)
- 612.1 Operating Techniques - Vortex generators (Speeds, Flutter, Buffet)
- 613.1 General Discussion - What it is coming to (Humor link)
- 614.1 Parts & Repairs - Caulking before painting
- 615.1 General Discussion - Great Lakes seaplane destinations
- 616.1 Parts & Repairs - off and on charging (Alternator, Air hose, Regulator, Connections, Circuit breakers, Shock mount)

June 2003

- 617.1 General Discussion - Flying northern British Columbia, Canada
- 618.1 General Discussion - Looking for plane/instructor in Vermont!
- 619.1 General Discussion - Vancouver Island destinations
- 620.1 General Discussion - Strakes and Bat Wings
- 621.1 General Discussion - Lake photos (Seawolf/renegade computer game)
- 622.1 Parts & Repairs - Messy oil and filter changes (Fuel filter)
- 623.1 Operating Techniques - Confidence in flying (Procedure, Trim mirror, Lake logo)
- 624.1 General Discussion - Starter problem (Removal, Bendix)
- 625.1 Parts & Repairs - Hundreds of Lake parts available
- 626.1 Operating Techniques - Engine needs to be leaned?
(Idle mixture, Oil fouling, Plugs, Harness, Injection nozzles)
- 627.1 Operating Techniques - Extra space in the middle seats (Seat tracks)
- 628.1 General Discussion - Why we call our Lakes 'She'
- 629.1 General Discussion - Free logo thought you would enjoy
- 630.1 General Discussion - Logo
- 631.1 Operating Techniques - Hot-running Lake (EP cowl, oil cooler, Turbo operation)
- 632.1 Fly-In Notices - Michigan Otsego Lake Fly-in (Landing/takeoff contest)
- 633.1 General Discussion - Technical question (Partial gear extension in water)
- 634.1 Fly-In Notices - Oshkosh
- 635.1 General Discussion - Micco
- 636.1 General Discussion - Annual in the Nashville TN Area
- 637.1 Operating Techniques - Marine radio
- 638.1 Parts & Repairs - Elevator trim control springs breaking
- 639.1 General Discussion - Thanks (Skimmer brochure)
- 640.1 General Discussion - Renegade useful load
(Weight, CG, Testing, Tire pressure, Aux fuel restriction, Flight manual,)
- 641.1 Parts & Repairs - Stripped threads in sheet metal
- 642.1 Operating Techniques - Water in hull (Nose gear hinge leak,)
- 643.1 Club Information - Lake seaplane for sale again?
- 644.1 General Discussion - Tyres (Larger tires)
- 645.1 General Discussion - Auto Pilots (STec 55)
- 646.1 Operating Techniques - Warning - all Lake "useful load" (Weight)

- 647.1 **Operating Techniques - Landing and taking off on snow!**
- 648.1 **Fly-In Notices - LAFC Annual meeting & Fly-in**
- 649.1 **General Discussion - Lake Pilot EAA Director!**
- 650.1 **Fly-In Notices - Killarney Canada Fly-In**
- 651.1 **Fly-In Notices - Stillwater Landing**
- 652.1 **Club Information - Stabler - Contact me**
- 653.1 Does not exist
- 654.1 **General Discussion - Article in GB magazine** (Trans-Atlantic ferry flight)
- 655.1 **Parts & Repairs - Knee through the windshield** (Source, Hatch, Canopy)
- 656.1 **Parts & Repairs - Alternator / regulator trouble**
(Over voltage, Connections, Shock mount, Hydraulic pump, Motor,)
- 657.1 **General Discussion - Aircraft parts - industrial art** (Link)
- 658.1 **General Discussion - Where is #16 and 18?** (Skimmers)
- 659.1 **Club Information - Maps on the internet?**
(Aeroplanner, Flitesoft, Toporama, Jeppesen, Topozone)
- 660.1 **Fly-In Notices - Stillwater Landing in Aug.**
- 661.1 **Operating Techniques - Depth of water** (Gear down)
- 662.1 **Parts & Repairs - Relief valve**
- 663.1 **Parts & Repairs - Door latch help**
- 664.1 Does not exist
- 665.1 **General Discussion - Oshkosh solace**
- 666.1 **Parts & Repairs - Indicator lights** (Lamps, Cleaning, 1813, 1815, 1816)
- 667.1 **General Discussion - Trunnion kit** (Patch)
- 668.1 **General Discussion - Reflections on Oshkosh** (Seawind)
- 669.1 **General Discussion - Contact information** (Pete)
- 670.1 **General Discussion - Help for nothing?** (Thanks)
- 671.1 **General Discussion - Airframe time**
- 672.1 **Operating Techniques - Get-home-itis - another crash, the H-1**
- 673.1 **Operating Techniques - Windows security bugs**
- 674.1 **Parts & Repairs - Shimmy damper bushings** ,(Nose wheel bolt)
- 675.1 **Parts & Repairs - Broken nose gear support brace** (Shimmy dampener, Up light, crosswind)
- 676.1 **General Discussion - Seen on TV** (Member on 'Discovery Wings')
- 677.1 **Operating Techniques - Cross-wind landings**
- 678.1 **Parts & Repairs - Doors** (Latch, Handle)
- 679.1 **Parts & Repairs- Doors** (Latch, Handle, Hatch, Open)
- 680.1 **General Discussion - Moving LA 4 200**
- 681.1 **General Discussion - Excess oil consumption** (Chrome, Drain lines, Pressure, Backfire, Gasket, Nozzle, Fuel flow, prop, Ball regulator, Valve Guide leakage,)
- 682.1 **General Discussion - Paul Furnee** (Fuel pressure, Alternator, Bubbling/boiling noise)
- 683.1 **General Discussion - Refueling in Ohio**
- 684.1 **General Discussion - Beriev** (Links)
- 685.1 **General Discussion - Help** (Posting pictures)
- 686.1 **General Discussion - 110 octane racing fuel**
- 687.1 **General Discussion - Interesting website** (Skimmer history, Thurston, Lindblad)
- 688.1 **Parts & Repairs - Door locking stop** (Latch, Handle)

- 689.1 General Discussion - New Renegade 2 pricing
- 690.1 General Discussion - Shop talk (Humor)
- 691.1 Fly-In Notices - Greenville and Basin Harbor
- 692.1 Parts & Repairs - Oleo for Buccaneer (Need)
- 693.1 Parts & Repairs - A buddy needs a Buc prop for his 180
- 694.1 Operating Techniques - Decapitation of N8551Z (Engine separation, Step turn, Rough water)
- 695.1 General Discussion - Selling lake cheap
- 696.1 General Discussion - Painting a Lake
- 697.1 Does not exist
- 698.1 Parts & Repairs - Engine case IO 360 1400tt yellow tag
- 699.1 Parts & Repairs - Engine case IO 360 a1b 1400tt
- 700.1 Parts & Repairs - Yoke (Powder coat)
- 701.1 Club Information - Lake toy airplane on ebay
- 702.1 Parts & Repairs - M-20 air/oil separator
- 703.1 Parts & Repairs - Hydraulic pressure bleed down (Valves, O-rings, Leak, Procedure)
- 704.1 Parts & Repairs - windshield tint color?
- 705.1 Operating Techniques - How to trim ailerons (VG's, Rigging)
- 706.1 Fly-In Notices - NC Splash-In, end of September
- 707.1 For Sale & Wanted Ads - Give away (Not really)
- 708.1 Does not exist
- 709.1 General Discussion - New Lake owner questions
(-200 prop, VG's, Spark plugs, Dynamic balance, Docking)
- 710.1 General Discussion - Rough H2O -- Hydro-foil time
- 711.1 Club Information - Lake Easy - Ban on seaplanes
- 712.1 Fly-In Notices - Bahamas fly-in
- 713.1 Parts & Repairs - Pitot static trouble shoot
(Bugs, Screen, Aero Advantage, Vacuum pumps, Dynon EFIS-D10)
- 714.1 General Discussion - PC help (Link to 'tune up' site)
- 715.1 General Discussion - Hangars for Lakes
- 716.1 Parts & Repairs - Renegade engines (NTSB, TBO, Top overhaul, Lines, Hoses, preheat)
- 717.1 For Sale & Wanted Ads - Tri pacer or colt (Wanted to trade for his LA4)
- 718.1 Parts & Repairs - Trim tab & oil leaks (Dye check, Tab play)
- 719.1 For Sale & Wanted Ads - Looking for Buc prop
- 720.1 For Sale & Wanted Ads - 1967 LA-4 180 for sale
- 721.1 Parts & Repairs - LA4 oleo oil quantity (Hydraulic)
- 722.1 Parts & Repairs - Nose wheel damper (Shimmy)
- 723.1 Club Information - Falling prices (Destinations, Beriev BE-103,)
- 724.1 General Discussion - Why us Northerners like it here (Great Lakes, Ice flying)
- 725.1 Parts & Repairs - Autopilot
- 726.1 Operating Techniques - Beaching (Gear down, Seals, Downlocks, Vice Grip,
- 727.1 Fly-In Notices - Fun Fly-in at Lake Mead
- 728.1 Parts & Repairs - Wheel bearing grease (Shell Retinax HD2,)
- 729.1 General Discussion - Lake Amphibian Flyers Club T-shirt
- 730.1 Parts & Repairs - Indicator lights (LEDs)
- 731.1 General Discussion - LA4 tire pressure (Wing root fairing)

- 732.1 General Discussion - Strut pressure? (Snap noise, Rear wing-attach bolt,)
- 733.1 General Discussion - Lake rentals
- 734.1 Parts & Repairs - Missing spark plug
- 735.1 General Discussion - Engine missing or vibration?
(Leaning, Power settings, Cowl, Pylon struts, Braces, Mystery oil)
- 736.1 Operating Techniques - winter oil changes (Preheating, Tanis)
- 737.1 General Discussion - Bob Copeland? (Operation,)
- 738.1 Operating Techniques - Cabin heater question?
- 739.1 Parts & Repairs - Adding aux fuel to an older LA4-180
- 740.1 Operating Techniques - Glassy water
- 741 General Discussion - Lake flyers and younger women
- 742 General Discussion - Hans Vosteen
- 743.1 Operating Techniques - More on the auto -vs- av. gas dispute
- 744.1 General Discussion - Thanksgiving
- 745.1 Operating Techniques - Topping the tanks (Cam, Oil, Bladder, Hangers, vents, Collapse)
- 746.1 General Discussion - Paint
- 747.1 Operating Techniques - Airspeed indicator accuracy? (Stalls)
- 748.1 Operating Techniques - Early Lake brochures
- 749.1 General Discussion - Lake training
- 750.1 Operating Techniques - LA250 w/aft cg - improved performance! (Airspeed, Cruise, Trim position, Movable ballast, Water takeoff, Leaks, Plugs, Flight test)
- 751.1 Club Information - Next annual meeting - question
- 752.1 Fly-In Notices - Have you seen? (Link 'Places')
- 753.1 Club Information - Lake 250 model on Ebay
- 754.1 General Discussion - Pilots over 60 (Procedure, Checklist, Skill, Practice, Fuel filter, Adaptors)
- 755.1 Parts & Repairs - VG modifications
- 756.1 General Discussion - Instrument currency
- 757.1 Parts & Repairs - Electrical problems - alternator ? (Heat, Vibration, Balmar)
- 758.1 Parts & Repairs - RPM gauge (Cold, Lube, Cable, Mobil 1)
- 759.1 Operating Techniques - See your PDA again
- 760.1 General Discussion - 100 Years of Flight
- 761.1 General Discussion - Northstar GPS M3 (Antenna, Cowl, Garmin)
- 762.1 Does not exist
- 763.1 General Discussion - Janitrol heater (Fuel consumption)
- 764.1 Insurance - Insurance problem
- Jan 2004**
- 765.1 General Discussion - Happy New Year safe flying
- 766.1 Parts & Repairs - 1978 LA-4-200 Flap actuator (Leak, Removal)
- 767.1 General Discussion - Hydraulic fluid cleaner
- 768.1 Operating Techniques - Ramping (Stuck, Pull bridle, Procedure, Damage)
- 769.1 For Sale & Wanted Ads - Lake flight simulator
- 770.1 Parts & Repairs - Greasing the wheels
- 771.1 General Discussion - Hanger flying (Forced landings, Water contamination, No-flap, Freezing, Ice, Step turn, Circular takeoff, Let others land your plane?)
- 772.1 General Discussion - Floor boards (Removed for flight, Water leaks)

| | |
|---|--|
| 773.1 Parts & Repairs - Partial paint job | (Sanding, Silicone, Masking tape) |
| 774.1 General Discussion - l.lalomong CD | (Flight simulator) |
| 775.1 General Discussion - Amphibious ramps | (Geofabric) |
| 776.1 General Discussion - Frozen runway | (Ice) |
| 777.1 Fly-In Notices - Montana Splash I | |
| 778.1 General Discussion - Survival training | (Egress) |
| 779.1 Parts & Repairs - Hull trouble | (Rib, Bulkhead) |
| 780.1 Parts & Repairs - Maintenance manual | |
| 781.1 General Discussion - Water lift | |
| 782.1 General Discussion - Aircraft registration fees | |
| 783.1 General Discussion - Article about New Lake | |
| 784.1 General Discussion - Auburn Washington | (Stillwater Fly-in dates) |
| 785.1 General Discussion - Down-climb | (Sink, Microburst) |
| 786.1 General Discussion - Irish pilots | (Humor) |
| 787.1 For Sale & Wanted Ads - Lake rental in Alaska | |
| 788.1 General Discussion - Gear advisory system | (Lake & Air) |
| 789.1 Fly-In Notices - Welcome to Winter Haven! | |
| 790.1 General Discussion - Arctic trip 2003 | (Canadian charts, Link to pictures) |
| 791.1 Does not exist | |
| 792.1 General Discussion - AWOS Anywhere | (Link) |
| 793.1 Parts & Repairs - More comfortable seats | |
| 794.1 General Discussion - Lake resale prices | |
| 795.1 General Discussion - Measurement question | (water depth) |
| 796.1 Club Information - 2004 Lakeathon | (Video tapes, Sponsons) |
| 797.1 Parts & Repairs - Fuel cell | (Eaglefuelcell, Filter) |
| 798.1 General Discussion - An unusual takeoff | (Parking brakes, Lake photo collection CD) |
| 799.1 General Discussion - Carburetor back-fire | (Air filter, Gear-down clearance in water) |
| 800.1 Fly-In Notices - Lake Mead Fly-in | |
| 801.1 Parts & Repairs - Wheel bearings | |
| 802.1 General Discussion - SES Time | |
| 803.1 General Discussion - Flap arm cushions | |
| 804.1 Operating Techniques - Interesting take-off; fuel pump off | |
| (Waste gate, Controller, Stain from vent, Landing light Plexiglas) | |
| 805.1 General Discussion - Texas flying | |
| 806.1 Parts & Repairs - Sponson leaks | (Testing floats) |
| 807.1 General Discussion - Canadian LA4-200 crash | (Gear-down water landing, Louisiana, 250) |
| 808.1 Fly-In Notices - Alaska trip | (Firearms, Bears, Survival equipment) |
| 809.1 Operating Techniques - Transponder antenna locations | |
| 810.1 Parts & Repairs - Lake exhaust | (Cracks, Welding) |
| 811.1 General Discussion - Satellite phones | (Globalstar, Iridium) |
| 812.1 Parts & Repairs - Diesel engine | |
| 813.1 Club Information - newsletter issue 04-2 | |
| 814.1 General Discussion - 180 settings | (Power, Airspeed, Heater, Weight) |
| 815.1 General Discussion - Sore subject - A. Rivard | (Lawsuit to recover Lake) |
| 816.1 General Discussion - Floating ramp | (Sunstream, Link) |

- 817.1 **Parts & Repairs - I need cash** (Floats for sale, C-1 parts)
- 818.1 **General Discussion - Grease-Corrosion X**
- 819.1 **Operating Techniques - Stall awareness** (Aerobatics, Spins, Coordination, Unusual attitude)
- 820.1 **Parts & Repairs - Engine overhaul surprise** (Cam, Pre-oiler, -6 crankshaft, IO360A1B6)
- 821.1 **Operating Techniques - Tight turns**
- 822.1 **General Discussion - Pacific Northwest**
- 823.1 **For Sale & Wanted Ads - Renegade wing for sale**
- 824.1 **Parts & Repairs - Pictures of recent paint job** (VG's)
- 825.1 **For Sale & Wanted Ads - Piece of history** (C-1, s/n 3)
- 826.1 **General Discussion - Discussion index**
- 827.1 **Fly-In Notices - Warning about Grand Marais**
- 828.1 **General Discussion - The Renegade with glass panel.**
- 829.1 **Parts & Repairs - Spinner for LA4-200**
- 830.1 **General Discussion - Australian AD** (Elevator control tube, Boots, Rudder bellcrank bracket)
- 831.1 **For Sale & Wanted Ads - Buccaneer propeller**
- 832.1 **General Discussion - Buc/EP Vs Renegade**
- 833.1 **General Discussion - Nice link** (AWOS info)
- 834.1 **For Sale & Wanted Ads - Abandoned or derelict Lake aircraft** (Wanted)
- 835.1 **For Sale & Wanted Ads - Aux fuel floats / autopilot** (Wanted)
- 836.1 **Fly-In Notices - Lake Russell voluntary closure**
- 837.1 **General Discussion - I sold mine on eBay!** (Automobile)
- 838.1 **Club Information - Web Forum Problems**
- 839.1 **Operating Techniques - Staying 'water current'** (Engine overhaul, Stoppage, Injector)
- 840.1 **Operating Techniques - Towing a Lake**
- 841.1 **General Discussion - Q tip vs straight blade prop** (Cut skin, turtle deck, Clearance)
- 842.1 **General Discussion - Identify this location** (Ramp)
- 843.1 **General Discussion - Landing ramps**
- 844.1 **For Sale & Wanted Ads - Ebay** (Buccaneer for sale)
- 845.1 **Operating Techniques - Bounce landings**
- 846.1 **General Discussion - Lake T-shirts, etc**
- 847.1 **General Discussion - Dual Chamber Vacuum pumps pulled from market** (Aerodvantage)
- 848.1 **For Sale & Wanted Ads - C-1 #17, N257B** (Skimmer project for sale)
- 849.1 **General Discussion - Main Gear Struts** (How much piston should show?)
- 850.1 **General Discussion - Batteries** (AGM, Concorde, Trickle, Maintainer)
- 851.1 **Operating Techniques - Is prop cleanliness next to godliness?** (Rate of Climb, Performance)
- 852.1 **Parts & Repairs - HOT ROD Lakes**
- 853.1 **General Discussion - Nature's Vgs**
- 854.1 **General Discussion - Tie Downs**
- 855.1 **General Discussion - Annual Inspection** (Modifications, Improvements, Equipment)
- 856.1 **General Discussion - Control Locks - Windshield covers**
- 857.1 **Parts & Repairs - change a tire?** (Fix-a-flat)
- 858.1 **General Discussion - Nose Gear Lesson**
(Beaching, Stuck, Cocked, Indicator lights, Switches, Shimmy)
- 859.1 **Operating Techniques - fuel consumption** (Economy, Power settings, Leaning, Flow, Restrictions, Over square, Performance, Engine operation,)

June 2004

- 860.1 Fly-In Notices - Otsego Lake Splash-In**
- 861.1 Fly-In Notices - Grand Marais, Michigan Splash-In**
- 862.1 Operating Techniques - Lake accident synopsis** (Link, UK)
- 863.1 Does not exist
- 864.1 Does not exist
- 865.1 Fly-in Notices - Speculator 2004**
- 866.1 Insurance - Rate Reduction**
- 867.1 Parts & Repairs - Fuel Bladder** (Gauge, Float, Transmitter, Transducer)
- 868.1 For Sale & Wanted Ads - Swap Comanche for Lake**
- 869.1 General Discussion - power** (Lanshe)
- 870.1 Does not exist
- 871.1 General Discussion - Stealth landing ramps** (GE4509, 4595,)
- 872.1 Parts & Repairs - Landing/taxi lights**
- 873.1 Operating Techniques - Landing Technique**
(Gear collapse, Fold, Hydraulic pressure, Float damage, Checklist)
- 874.1 General Discussion - Lake 'Service Centers'** (Lanshe)
- 875.1 General Discussion - Smoke Marker** (Glassy, Hatch open inflight, Wingwalk)
- 876.1 Parts & Repairs - Nose Gear Doors Wanted**
- 877.1 General Discussion - Modified Buccaneer** (Super Buc, Dale Schoepflin, Palouse)
- 878.1 Operating Techniques - Fuel consumption**
- 879.1 Operating Techniques - Flying solo from left seat**
- 880.1 General Discussion - S/N 12** (Skimmer)
- 881.1 General Discussion - Oil leak** (Annual, Mechanic, Automatic bilge pump,, Hull water level)
- 882.1 Does not exist
- 883.1 Parts & Repair - Hidden danger** (Baggage compartment, Condensation, Corrosion, Vent fan)
- 884.1 General Discussion - Trolling motors** (Battery)
- 885.1 Parts & Repair - Fuel odor**
(Quick drain manifold, Block, Bladder fittings, Dye, Stain, Sealant, Flare,)
- 886.1 General Discussion - LA4 fatal crash** (NTSB report, VFR in IMC,)
- 887.1 General Discussion - For Fun** (Web site for helicopter game)
- 888.1 General Discussion - Wadi Rahim - Lake saga**
- 889.1 Parts & Repair - Old hydraulic pump** (Overhaul, Aero Electric)
- 890.1 General Discussion - Water lifts**
- 891.1 General Discussion - Price of Avgas vs diesel**
- 892.1 General Discussion - Lake service facilities**
- 893.1 Fly-In Notices - Kalispell/Whitefish meet in Aug**
- 894.1 General Discussion - Canopy covers**
- 895.1 General Discussion - June mishap in LA4-250** (Accident, Step landing, Underwater egress)
- 896.1 For Sale & Wanted Ads - Lake needed** (Prices)
- 897.1 General Discussion - Gami injectors** (Fuel flow, EGT readings)
- 898.1 Does not exist
- 899.1 General Discussion - Temporary Long Range Fuel Tanks** (Ferry,)
- 900.1 Fly-In Notices - EAA Airventure 2004 Oshkosh** (Spinner)
- 901.1 Parts & Repair - Hydraulic Consternation** (Relief valve, Pressure switch, Pump current/drain)

- 902.1 General Discussion - Bouyancy Numbers**
- 903.1 Parts & Repair - Prop balancing** (Renegade Rumble, Pylon flying wires, Dynamic balance)
- 904.1 General Discussion - Just for the fun of it!** (Baffin Island trip, Saint-Exupery)
- 905.1 General Discussion - Rain-X**
- 906.1 General Discussion - Auxiliary Power plug**
- 907.1 Parts & Repair - Engine vibration** (Wires, Prop balancing)
- 908.1 Fly-In Notices - Splash this weekend** (Stillwater Landing)
- 909.1 General Discussion - Something new** (Magazine article on a ground-effect seaplane)
- 910.1 Operating Techniques - Flight level flying** (Turbo operation & leaning, Oxygen)
- 911.1 Operating Techniques - Flight level flying** (Continuation of 910)
- 912.1 General Discussion - South Florida** (Hurricane, Magnetic particles in the filter)
- 913.1 General Discussion - Florida** (More hurricane)
- 914.1 Operating Techniques - Almost flight levels**
- 915.1 Fly-In Notices - Flying to see Fall Colors in Kentucky**
- 916.1 General Discussion - Magazine** (Old issues of Water Flying Magazine available.)
- 917.1 General Discussion - Lasar ignition**
- 918.1 Operating Techniques - True Airspeed** (Performance)
- 919.1 General Discussion - CHT gauge** (Diagnosis, Probes, Insight Gem, JPI)
- 920.1 General Discussion - LA4-200 Accident** (Lake Oroville)
- 921.1 General Discussion - Lake Oroville crash** (Bounce)
- 922.1 Parts & Repair - Help! Hydraulic question** (Level, Overflow, Vent, Testing, Pump)
- 923.1 Parts & Repair - Oil types** (Multigrade, Exxon Elite, Aeroshell)
- 924.1 General Discussion - Buc Prop**
- 925.1 General Discussion - Top overhaul vs Total Rebuild**
(Cam, Dampened, BalanceCylinders, MT prop, Performance off-the-water,
Tach calibration, Fuel flow, Weight, Static thrust, Changing forum E-mail address)
- 926.1 General Discussion - Renegade vs Buccaneer** (Performance, Hull length-to-width,
Water handling, Useful load, Beriev BE-103 flight report)
- 927.1 General Discussion - Stealth Ramp** (Hanger, Erect-a-Tube, Cost, Price)
- 928.1 Operating Techniques - Night water landings** (Landing lights, Nose down)
- 929.1 General Discussion - Compilation of water landing sites** (Links, SPA, Restricted, Prohibited)
- 930.1 Parts & Repair - Contact search** (Bob Copeland)
- 931.1 General Discussion - Hurricane Frances**
- 932.1 General Discussion - Flying Texas to Washington** (Routes, High altitude, Mountain)
- 933.1 General Discussion - Combo tach & MP gauge?** (Panel layout)
- 934.1 Does not exist
- 935.1 General Discussion - Turbo 270** (Comparison with 250, Performance)
- 936.1 Parts & Repair - Tired relief valve** (Pressure, Hydraulic)
- 937.1 General Discussion - Hurricane Ivan "The Terrible"**
- 938.1 General Discussion - Hurricanes & Ferry pilots**
- 939.1 General Discussion - Videos** (Lubrication)
- 940.1 General Discussion - Fuel capacity, bilge pump**
(Water level, Auto switch, Relocating, Mounting, Bilge Buddy)
- 941.1 Fly-In Notices - Killarney Fly-in**
- 942.1 Parts & Repair - Parts available**

- 943.1 General Discussion - Lake factory
- 944.1 General Discussion - How far can a man walk? (Wing, Capsize, Floatation)
- 945.1 General Discussion - Renegade weight and balance (CG)
- 946.1 General Discussion - Here we go again (Another hurricane)
- 947.1 Parts & Repair - EC electronic tach (Horizon,)
- 948.1 Operating Techniques - Lake accident (Training, Instruction, Finland)
- 949.1 General Discussion - Engine failure in my Renegade 270 T (Turbo scat tube collapse. see 1120)
- 950.1 Fly-In Notices - Winterhaven Lake meet
- 951.1 General Discussion - Life vests (Jackets, Spare Air)
- 952.1 For Sale & Wanted Ads - Q-Prop available
- 953.1 For Sale & Wanted Ads - Turbo
- 954.1 General Discussion - Visit the Sage (Cow windsock)
- 955.1 Parts & Repair - Cut that Filter
(Metal flakes, Ring land, Three cylinders, Injection nozzle, Airmaze, Cam,)
- 956.1 Operating Techniques - Short field ops (Soft, Soggy, VG's, Small lakes)
- 957.1 Operating Techniques - Lake product support (Bankruptcy, Claim)
- 958.1 Parts & Repair - "Spalling" (Cam, Lifter, Break-in oil, Collection can, Multigrade,
Breather hose location, Link to Sacramento Sky Ranch article, Engine removal)
- 959.1 General Discussion - Deer story
- 960.1 General Discussion - We've been TSA'd (Background check, Training, Alien)
- 961.1 General Discussion - Landing gear question (Retraction time, Accumulator pressure)
- 962.1 General Discussion - Go to Hull download
- 963.1 General Discussion - Brittain vs S-Tec autopilot (Lake Powell pictures)
- 964.1 Operating Techniques - TFR Information (Link)
- 965.1 General Discussion - Instrument repair (DG, Turn & bank)
- 966.1 Operating Techniques - Winter oil change
- 967.1 Club Information - N271B
- 968.1 Club Information - N271B (Continuation of 967)
- 969.1 Parts & Repair - Electric heaters (DC Thermal.)
- 970.1 Parts & Repair - Not flying, Recent maint. items & tips (Problems)
- 971.1 Parts & Repair - Stainless steel brakes (Disks)
- 972.1 Does not exist
- 973.1 Parts & Repair - Collecting reliability data (Failure, Problems)
- 974.1 Operating Techniques - Trim setting (Spin, Engine failure)
- 975.1 Parts & Repair - Ramp done
- 976.1 General Discussion - Steve Reep's phone (Looking for 'Go to Hull' book)
- 977.1 General Discussion - Oil on the tail (Leaks, Consumption, Level, Prop seal, Proseal)
- 978.1 General Discussion - Seaplane friendly Oregon
- 979.1 Parts & Repair - Spalling (Continuation of 958)
- 980.1 Operating Techniques - A point to ponder (Control yoke, U-joint, Wires)
- 981.1 Parts & Repair - Electronic tach (Idle RPM, Mixture)
- 982.1 General Discussion - Three blade prop(MT, Hartzell EPR, Temperature, Composite, Repair)
- 983.1 Operating Techniques - Slipping a Lake (Isabel Lake, Diving approach, Rudder control bracket)
- 984.1 General Discussion - More Lake video (Promotional video from the 70's)
- 985.1 For Sale & Wanted Ads - Lake seaplane

- 986.1 Parts & Repair - Accumulators (Older spherical type available)
- 987.1 General Discussion - Buccaneer prop on 180 (Need 337)
- 988.1 General Discussion - Cabbage Key
- 989.1 Club Information - Ridiculous idea? (Link)
- 990.1 General Discussion - Sad news from Finland (H-Stab failure. Link: AD 98-12-10)
- 991.1 Parts & Repair - Failed electric fuel pump (Priming, Bottle, Air door, Syringe, Filter)
- 992.1 Operating Techniques - Aerodynamic drag (Link: formulas)
- 993.1 Operating Techniques - Engine preheating (Reiff, Continuous)
- 994.1 Parts & Repair - Electric cabin heater
- 995.1 Parts & Repair - Busted annual (Skybright, Aero Aircraft Services, Maintenance shops)
- 996.1 Operating Techniques - Lake 270T endurance (Performance, Altitude, Turbo,
Normally aspirated, Cruise, Cam, valve lift, Power settings, Power chart)
- 997.1 Parts & Repair - Missing SB/SL (Request for service bulletins and letters)
- 998.1 General Discussion - 4 Forces of Aviation (Humorous picture)
- 999.1 Parts & Repair - Lake signs or artwork
- 1000.1 General Discussion - Cabin cover
- 1001.1 General Discussion - DC Thermal heater (Oil, Morocycle suit, Ceramic, Car seat)
- 1002.1 General Discussion - AOPA's 2005 plane
- 1003.1 Parts & Repair - Spalling (TBO, Metal flakes, contamination, Chrome, engine angle)
- 1004.1 Parts & Repair - Hydraulic lines (Size / part number)
- 1005.1 Club Information - Airsure insurance (E-mail address)
- 1006.1 Parts & Repair - Wing walk (Non skid, Sand, Roof reinforcement/doubler)
- 1007.1 General Discussion - Jump in a Lake (Looking for 'Go to hull' download)
- 1008.1 Operating Techniques - Using sponson tanks
(Transfer time, Gas caps, Wing tanks, Unbalanced weight, Asymmetrical loading)
- 1009.1 Operating Techniques - Oil separator / bypass (Water, Oil level in Renegade)
- 1010.1 General Discussion - Here's what we need (Aero Commander to seaplane again)
- 1011.1 For Sale & Wanted Ads - Southwind heater (Thermostat, Glow plug/igniter,)
- 1012.1 General Discussion - Splash/Camp in the Everglades?
- 1013.1 For Sale & Wanted Ads - LA-200 for sale
- 1014.1 Parts & Repair - Alternator issues/wiring (Marine, Regulator, Single-wire)
- 1015.1 Club Information - Red painted Lake (Link)
- 1016.1 General Discussion - Lake lift points/lugs
- 1017.1 Parts & Repair - Lake sponson/float on Ebay
- 1018.1 Club Information - Lake video (Continuation of 984)
- 1019.1 Fly-In Notices - Our Convention at Winterhaven
- 1020.1 Operating Techniques - Danger! (Tower / power line hazards)
- 1021.1 General Discussion - Christmas
- 1022.1 General Discussion - Washington seaport closure (American Lake, Lakewood, Wa)
- 1023.1 Operating Techniques - 2005 New Year's resolutions
- 1024.1 Club Information - Movie "Aviator"
- 1025.1 Parts & Repair - Eyeball air vents (Need source for gaskets)

Jan 2005

- 1026.1 Parts & Repair - New prop AD for LA4?
- 1027.1 Operating Techniques - Alert to pilots: Wing upper surface ice

- 1028.1 General Discussion - Preventive maintenance
- 1029.1 General Discussion - Vinyl cleaning suggestion
- 1030.1 For Sale & Wanted Ads - Skimmer C-3 for sale (C-1, Serial number 3)
- 1031.1 Parts & Repair - Build a work stand (Cam, Spalling)
- 1032.1 Parts & Repair - Southwind heater (Want)
- 1033.1 For Sale & Wanted Ads - Jacks for sale (Sold)
- 1034.1 General Discussion - Micco (Company up for auction)
- 1035.1 Does not exist
- 1036.1 Operating Techniques - TSA awareness training for CFIs by Jan 18
- 1037.1 General Discussion - Puddle Jumper's new AOL address
- 1038.1 Operating Techniques - LASERs: NORAD's got a "good" one
- 1039.1 Fly-In Notices - Lake apparel
- 1040.1 Operating Techniques - Renegade landing technique (Full stall,)
- 1041.1 Operating Techniques - Dumb stunt (Picture of inverted low pass)
- 1042.1 Parts & Repair - Theoretical question about engine starts (Normal hot start)
- 1043.1 Parts & Repair - Wanted - down-draft system for Lycoming
- 1044.1 Operating Techniques - Wrong advice in Lakeflyers - oil levels
- 1045.1 General Discussion - West to east (Stopover spots)
- 1046.1 Fly-In Notices - Looking for a lift (to Winterhaven)
- 1047.1 For Sale & Wanted Ads - Intercoms and headsets
- 1048.1 General Discussion - Kid's life vests
- 1049.1 Fly-In Notices - 2005 Lake-a-Thon (180-200 prop comparison in 1049.50)
- 1050.1 For Sale & Wanted Ads - 180 prop for sale
- 1051.1 Club Information - Lakeathon (Continuation of 1049)
- 1052.1 General Discussion - 2 Drain holes (Brown streak/stain)
- 1053.1 General Discussion - Small world department
- 1054.1 General Discussion - Large lakes, e.g. Lake Okeechobee
(Middle of, Swells, Judging wave height & period, Wavelength)
- 1055.1 Operating Techniques - Gear or flaps first on land landings? (Operation, Procedure, ILS)
- 1056.1 General Discussion - 180 carburetor (Stains, Vents, Location)
- 1057.1 General Discussion - Prop overhaul
- 1058.1 General Discussion - Video recording in a Lake
- 1059.1 General Discussion - Are step turns dangerous?
- 1060.1 Club Information - Get out of jail free card (ASRS, Aviation Safety Reporting System)
- 1061.1 Parts & Repair - Need a good used rubber nose bumper
- 1062.1 General Discussion - Oil temp (Need sending unit)
- 1063.1 General Discussion - High EGT reading (Alcor gauge adjustment, Mixture, Timing)
- 1064.1 General Discussion - Sad news (Lake pilot in fatal C-182 accident)
- 1065.1 Operating Techniques - Crosswind water landings
- 1066.1 Club Information - Destinations?
- 1067.1 Club Information - Horizontal Stabilizer support cracking.
- 1068.1 General Discussion - Humidity (Ventilation fan,)
- 1069.1 Club Information - Condo available for next Lakeflyers (Turbo Renegade performance)
- 1070.1 General Discussion - Personal discussions
- 1071.1 Club Information - Lake seaplane on Ebay again!

- 1072.1 General Discussion - Free FAA training courses online (Link)
- 1073.1 General Discussion - Need for speed (Large Beriev amphib)
- 1074.1 Parts & Repair - New Lycoming mandatory SB565 (Fuel pump)
- 1075.1 For Sale & Wanted Ads - Manuals for sale (LA4-180 & -200)
- 1076.1 Parts & Repair - Lycoming service bulletins on the Web (Link)
- 1077.1 General Discussion - Flying magazine (Is the Lake safe or difficult to fly?)
- 1078.1 General Discussion - Weight & Balance (Links, American Aeronautics plotter,
Garmin 196, ControlVision, Ballast, Battery, CG,Tools, Equipment box)
- 1079.1 Parts & Repair - Dukes fuel pump (Seals, Weldon 8120,)
- 1080.1 Club Information - XLSCO (Praise for Bob Copeland)
- 1081.1 General Discussion - Horiz Stab attachment update (Request for information)
- 1082.1 Parts & Repair - Q prop still available (Hartzell hub SB/AD, MT repair, Overhaul)
- 1083.1 Fly-In Notices - Join Alaska adventure in June
- 1084.1 General Discussion - Lake pilot flies medicines to Cuba! (Link)
- 1085.1 General Discussion - New instrument procedures handbook
- 1086.1 General Discussion - New to Lake
- 1087.1 General Discussion - Lake info on web (Link, LED gear/flap lights)
- 1088.1 General Discussion - Lake-a-thon photo
- 1089.1 Parts & Repair - Fuel sending unit (Collapsed bladder, Transducer, Goodyear
Cleveland brakes, VG's, Fuel flow, Leaning, Burble, Root fairings, Cleaning tank, Filler neck)
- 1090.1 General Discussion - Hanger door choice (Hydroswing, Schweiss, Charles Edwards, Wilson)
- 1091.1 General Discussion - Eagle sensitive areas
- 1092.1 General Discussion - Flying without sponsons
- 1093.1 General Discussion - Status of Appeal (Wing spar patent)
- 1094.1 Operating Techniques - Glassy water (Practice, Debate)
- 1095.1 Operating Techniques - Turbo 270 power chart (Power setting, flow)
- 1096.1 Does not exist
- 1097.1 General Discussion -Lake Como Aero Club Information (Link)
- 1098.1 Parts & Repair - EFIS (Dynomavionics, Bluemountainavionics, ControlVision)
- 1099.1 Does not exist
- 1100.1 Club Information - Lake sale (Lake company at auction)
- 1101.1 Parts & Repair - Drifting trim & other news (Air in hydraulic line)
- 1102.1 General Discussion - BC routes (Canadian weather Link)
- 1103.1 Destinations - New folder
- 1104.1 Parts & Repair - SB listings (Request)
- 1105.1 General Discussion - SEL rating with Lakes
- 1106.1 Club Information - Next Lakeflyers meeting idea (Fantasy of Flight facility)
- 1107.1 General Discussion - Prop smudge (Cleaning exhaust, WD-40, Wash Wax All)
- 1108.1 For Sale & Wanted Ads - Wanted, Go To Hull book
- 1109.1 Operating Techniques - Displacement turns in Renegade (Strobes, Float filler cap)
- 1110.1 General Discussion - Seaplane Expo in Naples, ME
- 1111.1 Fly-In Notices - Otsego Lake Splash-In (Battery maintainer, Trickle charger)
- 1112.1 Operating Techniques - A Buccaneer in BC (Video)
- 1113.1 Parts & Repair - Fuel bladder (Snaps)
- 1114.1 Operating Techniques - Takeoff trim setting (Renegade)

- 1115.1 General Discussion - Unusual uses
- 1116.1 Parts & Repair - Renegade wheel bearings (OMC boat trailer grease, Removing races)
- 1117.1 For Sale & Wanted Ads - 200 prop for sale
- 1118.1 For Sale & Wanted Ads - Lake Beresford
- 1119.1 Operating Techniques - Emergency 180 (Turning back. See 1120)
- 1120.1 Operating Techniques - Emergency 180 (Article, Collapsed turbo scat tube. See 949)
- 1121.1 General Discussion - Another interested Lake flyer
- 1122.1 Destinations - Everglades City Rod and Gun Club

June 2005

- 1123.1 General Discussion - Sweatshirts
- 1124.1 For Sale & Wanted Ads - 180 hp O-360-A1A engine for sale
- 1125.1 General Discussion - Little humor in everything (Nesting eagles)
- 1126.1 For Sale & Wanted Ads - 180 prop for sale
- 1127.1 For Sale & Wanted Ads - 1979 Lake Buccaneer (E-bay, Market price?)
- 1128.1 General Discussion - LA4-200 Performance (Cross country, Buying a Lake, annual costs)
- 1129.1 Parts & Repairs - Stab AD (Horizontal stabilizer AD 2005-12-02, see also 1081)
- 1130.1 Destinations - Alaska trip (Continuation of 1083)
- 1131.1 Destinations - Ashland Wisconsin, dock, beach, motel
- 1132.1 Parts & Repairs - Turbo charger for Buc (Any available?)
- 1133.1 General Discussion - 180 Turbo? (Need make & model of the engine-driven fuel pump)
- 1134.1 General Discussion - Stab. AD (Continuation of 1129)
- 1135.1 General Discussion - Lake video (Flying in British Columbia, See also 1112)
- 1136.1 Parts & Repairs - LA4-200 average annual costs (Cam wear, Broken oil ring, Insurance)
- 1137.1 Parts & Repairs - Alternator update (Failure, Marine, Heat)
- 1138.1 Operating techniques - Low-noise takeoff in a Renegade (Power settings)
- 1139.1 General Discussion - New Lake owner
- 1140.1 General Discussion - Average useful loads (Empty weight)
- 1141.1 General Discussion - Any Lake Flyers in SW Wash?
- 1142.1 General Discussion - Battery maintenance-charging (Power plugs. RG battery life.)
- 1143.1 Operating Techniques - 'No-flap' take-offs (Water experience)
- 1144.1 General Discussion - MT prop. and gov. (Performance, Vibration, Noise)
- 1145.1 Operating Techniques - Weight and balance computing (See 1078.)
- 1146.1 General Discussion - Buccaneer crash (NTSB, Maneuvering flight)
- 1147.1 General Discussion - Slipping throttle
- 1148.1 Destinations - Speculator, NY
- 1149.1 Destinations - Basin Harbor, VT
- 1150.1 General Discussion - New Skimmer owner
- 1151.1 Club information - details Buccaneer crash look at buccanee (See 1146.)
- 1152.1 Club information - Update on last year's fatal Buc incident (Link to NH crash.)
- 1153.1 General Discussion - Renegade fuel consumption (Power settings, Flow, Leaning, TIT, EGT, CHT probes, Detonation, EP burn, MP vs RPM restriction, MT RPM restriction, A1B6, Tach error, Digital checker, Turbo, Renegade rumble, Wires)
- 1154.1 Parts & Repairs - Tail skid
- 1155.1 Parts & Repairs - Lycoming crankshaft problems again (Link, SB566)
- 1156.1 Club information - Bang! (Taxi accident)

- 1157.1 General Discussion - Horizontal tail fittings
- 1158.1 General Discussion - Your grandmother (Skimmer)
- 1159.1 Destinations - Greenville Maine
- 1160.1 Parts & Repairs - Camshaft spalling
- 1161.1 General Discussion - Garmin 396 (XM weather)
- 1162.1 General Discussion - LA4-200 fuel consumption
- 1163.1 General Discussion - Revo, Lan-She, now “the highest bidder”
- 1164.1 General Discussion - Confessions (Lost dipstick, Gear-up ramping, Rudder lock,)
- 1165.1 Does not exist
- 1166.1 Club Information - Lake crash (See 1146.1)
- 1167.1 Parts & Repairs - Super-bright landing lights (HID, Right wing, Skimmer history)
- 1168.1 Operating Techniques - Take off distances, land/water
(Density altitude, Reduced MP, Wakes & swells, Floatplanes vs flying boats)
- 1169.1 Club information - Lake auction (Company auction, Factory support, Field approval)
- 1170.1 General Discussion - Change E-mail? (Change address on Forum)
- 1171.1 General Discussion - Humming sound on takeoff
- 1172.1 Fly-in Notices - Our Lake Flyers meet - Feb. 06
- 1173.1 Parts & Repairs - Alternator noise (Connections, Circuit breaker, Jumper wire)
- 1174.1 General Discussion - Lake aircraft brokers
- 1175.1 General Discussion - What an airplane! (Trip description. Power settings)
- 1176.1 For Sale & Wanted Ads - For Sale and wanted ads (Looking for -200 and Renegade)
- 1177.1 Operating Techniques - EGT spiking (Probes)
- 1178.1 General Discussion - More on humming
- 1179.1 General Discussion - Lake instruction (Instructor ratings, Requirements)
- 1180.1 Club information - ‘Lake’ sport aircraft (Links, Mermaid, Xavier)
- 1181.1 For Sale & Wanted Ads - Wanted (Cargo door)
- 1182.1 Operating Techniques - Need some VG information (Batwings, Density altitude, Airspeeds, Test procedure, Modifications)
- 1183.1 General Discussion - Flying boat dock at Oshkosh
- 1184.1 Club Information - Constant-wear personal flotation devices
- 1185.1 General Discussion - Who goes there? (Identify Lake at Soldatna)
- 1186.1 Operating Techniques - Main gear retraction (Problem, Indicator light)
- 1187.1 Parts & Repair - Engine Condition (Cylinder thru bolt oil leaks, Black oil)
- 1188.1 General Discussion - Info on LA4-200 N65683 S/N 602 (A/C info-history)
- 1189.1 Club Information - Lake-A-Thon 2006 Dates (Fantasy of Flight)
- 1190.1 Wing AD - AD 2005-12-02 Extension (H-stab extension contact information)
- 1191.1 General Discussion - Lake Sale (Company?)
- 1192.1 General Discussion - Moving things
- 1193.1 Destinations - ELO, MN
- 1194.1 Operating Techniques - Restricted RPM range operations (Leaning, MT prop)
- 1195.1 General Discussion - Have you ever noticed? (Humor, Anecdotes)
- 1196.1 Club Information - Tony Onley (Lake pilot/artist, RIP)
- 1197.1 Parts & Repair - Engine ‘ring mount’ (Crack in upper cowl-frame support)
- 1198.1 General Discussion - AD 2005-12-02 (Horizontal stabilizer)
- 1199.1 For Sale & Wanted Ads - O360 Engine for sale
- 1200.1 Fly-in Notices - Killarney Fly-in

- 1201.1 Club Information - SPA annual meeting**
- 1202.1 General Discussion - AD 2005-12-02 parts**
(AMOC. H-stab compliance extensions, Trim tab play)
- 1203.1 Parts & Repair -Alternator switch replacement**
(Noise, Grounding, Circuit breaker, Connections, Wiring)
- 1204.1 For Sale & Wanted Ads - Looking for sponson**
- 1205.1 Parts & Repair - Loose engine parts** (Prop ding, Wing hole, Valve cover bolts, Studs)
- 1206.1 General Discussion - Hurricane Katrina**
- 1207.1 General Discussion - Mystery object** (Found in engine cowl.)
- 1208.1 General Discussion - Spam mail alert** (E-mail non-delivery.)
- 1209.1 General Discussion - Advice on my flight home** (Anchorage to Kansas City, 1224)
- 1210.1 Parts & Repair - Engine pricing** (Overhaul)
- 1211.1 Parts & Repair - Time-Rite timing tool**
- 1212.1 Club Information - Aviation articles website** (Link)
- 1213.1 For Sale & Wanted Ads - LA4-200 for sale**
- 1214.1 For Sale & Wanted Ads - Great plane** (LA4-180)
- 1215.1 General Discussion - Dock help** (Floating, Jet Dock, Jet Float, MT prop in reverse)
- 1216.1 General Discussion - Garmin 396, anybody?**
(GPS, XM, Antenna mounting, Anywhere, Bluetooth)
- 1217.1 General Discussion - Boulder, Steamboat springs, Lake Powell**
(Membership directory request.)
- 1218.1 General Discussion - Handheld** (GPS, Comm)
- 1219.1 Parts & Repair - Engine cowling** (Modification for access.)
- 1220.1 Parts & Repair - Warning - Nose gear issue!** (Not a tow point.)
- 1221.1 Destinations - Google Earth** (Satellite photos)
- 1222.1 Parts & Repair - Hydraulic pump replacement** (Problems, Overhaul Aero Electric)
- 1223.1 Club Information - SPA annual meeting, Oct 27, Lakeland FL**
- 1224.1 General Discussion - My trip home** (Trip description. Continuation of 1209.)
- 1225.1 Destinations - Flying out west to San Francisco** (Route recommendations?, 1226.)
- 1226.1 General Discussion - East West crossing point?** (1225)
- 1227.1 Parts & Repair - Cargo door LA4-200** (Want)
- 1228.1 General Discussion - Ramp stuff**
- 1229.1 General Discussion - Lake auction live** (Link)
- 1230.1 Parts & Repair - Interior replacement** (Link)
- 1231.1 General Discussion - Battery problems** (Master relay)
- 1232.1 General Discussion - Micro VG's** (Airspeeds, Clearance, Root fairing)
- 1233.1 General Discussion - VG guard** (Cover)
- 1234.1 General Discussion - Thread sealer for drain plugs** (Titeseal)
- 1235.1 Parts & Repair - Landing lights** (HID, 337)
- 1236.1 General Discussion - Lake qualified examiner** (Michigan)
- 1237.1 For Sale & Wanted Ads - Lake 180 for sale or trade**
- 1238.1 For Sale & Wanted Ads - Two Lakes for sale**
- 1239.1 General Discussion - Mods/questions** (Oil drain tube, oil filler extension, folding rear seat)
- 1240.1 For Sale & Wanted Ads - Need autopilot**
- 1241.1 Parts & Repair - Need gas springs for canopy** (Door holder)
- 1242.1 Operating Techniques - Winterizing** (Tanis, Pre-heat)

- 1243.1 **Parts & Repair - Prop questions** (LA4-180, Tip clearance)
- 1244.1 **General Discussion - House/hanger combo**
- 1245.1 **Parts & Repair - Engine analyzer probes**
- 1246.1 **Parts & Repair - Alternator over-charging** (Regulator, Over voltage)
- 1247.1 **Parts & Repair -Hydraulic system** (Link, Troubleshooting, Trim handle sticking)
- 1248.1 **General Discussion - Wing-root fairings** (Cargo door)
- 1249.1 **General Discussion - Special gift has arrived**
- 1250.1 **General Discussion - Flat nose strut** (Nose door jam, Spring)
- 1251.1 **General Discussion - Warped valve on T-270**
- 1252.1 **Parts & Repair - An interesting? phenomena** (One-way leak in push-rod boots)
- 1253.1 **Club Information - Oct 27 SPA annual meeting, Lakeland FL**
- 1254.1 **Operating Techniques - So I tried a slip** (Lake Isabel, NTSB link)
- 1255.1 **General Discussion - Hurricane Wilma**
- 1256.1 **General Discussion - Clock replacement T-270** (Stormscope)
- 1257.1 **Parts & Repair -Roller tappets** (Cam, Metal in filter)
- 1258.1 **Parts & Repair - Stab AD update** (Looking for cost & hours-to-install estimates)
- 1259.1 **Operating Techniques - Instrument lighting** (Eyebrow, Post, Link, Dimmer)
- 1260.1 **Operating Techniques - Danger - tall tower alert**
- 1261.1 **For Sale & Wanted Ads - Parts for sale** (Hurricane damaged LA4-180) (1267.1)
- 1262.1 **General Discussion - Electric attitude indicator** (S-tec, 55X, Link)
- 1263.1 **For Sale & Wanted Ads - Parts for sale** (Wants LA4-200)
- 1264.1 **General Discussion - Salt water use** (1265.3, 1256.5, 1309.1)
- 1265.1 **Fly-in Notices - Montana** (Salt water)
- 1266.1 **Club Information - New LSA amphib and the FAA**
- 1267.1 **For Sale & Wanted Ads - Wreck from storm** (1261.1 and 1273.1) (Damage avoidance)
- 1268.1 **Club Information - Lake Flyers map showing where you live** (Pictures of our planes)
- 1269.1 **Parts & Repair - Salvaging the shimmy damper** (Cleaning)
- 1270.1 **Operating Techniques - Can I use automobile gas in my Lake?**
(Corrosion, CHT, Oil temperature, Ignition systems)
- 1271.1 Does not exist
- 1272.1 **For Sale & Wanted Ads -Headsets and intercom for sale**
- 1273.1 **Parts & Repair - last chance before Ebay** (1261.1 and 1299.1)
- 1274.1 **Operating Techniques - A real bad day** (Gear-down landing - amphib floatplane video)
- 1275.1 **Club Information - Lake 1065L** (Request for damage report)
- 1276.1 **General Discussion - Trim tab play** (Taper pin, Bolt,)
- 1277.1 **General Discussion - What type of battery should I use?** (Concorde, Trickle charge, Hot starts)
- 1278.1 **General Discussion - Bose headset** (Depth sounders)
- 1279.1 **For Sale & Wanted Ads - NEW Lake for sale (not a joke)** (Seafury being built)
- 1280.1 **General Discussion - Differential gear** (Nose up, mains down in water)
- 1281.1 **Parts & Repair -Second landing light**
- 1282.1 **General Discussion - Lake Buccaneer noise**
- 1283.1 **Club Information - List of activities at Lake-A-Thon**
- 1284.1 **General Discussion - New Lake owner - need help** (La4-180 performance, Weight, CG, Cam, Overhaul, Water takeoff technique, Engine/pylon removal, 1303.1)
- 1285.1 **General Discussion - Request for Lake model** (Desktop model, Link)
- 1286.1 **Parts & Repair -Magnetos** (Slicks or Bendix?, Engine & canopy covers)

- 1287.1 Club Information - New Lake flyer born
- 1288.1 Club Information - Finding Bob Stebbins
- 1289.1 Club Information - Lake Fliers map (Pictures)
- 1290.1 Operating Techniques - MT prop hub and cold weather warning (Spinner, Water)
- 1291.1 Parts & Repair -Possible prop AD on 200 hp prop (SB269, Hun, Eddy, MT)
- 1292.1 Parts & Repair -Ignition harness
- 1293.1 Operating Techniques - What fuel tanks to use (Landing load)
- 1294.1 Operating Techniques - Cold weather operations (Convective lift, Sink rate, Freezing, link)
- 1295.1 General Discussion - Matchbox Seafury (Toy)
- 1296.1 General Discussion - EAA Young Eagles program
- 1297.1 Operating Techniques - Never Again @ Moosehead lake (Splash guard, Glare shield)
- 1298.1 Parts & Repair - Repair-ability of MT propeller
- 1299.1 Club Information - Ebay Lake (1261.1)
- 1300.1 General Discussion - Lake-A-Thon lessons
- 1301.1 Club Information - The only Lake seaplane on Ebay again???
- 1302.1 Club Information - Lake vs Maule on floats.. (Leaks, Aft bilge pump)
- 1303.1 Parts & Repair -Engine removal (Accessories, 1284.1)
- 1304.1 General Discussion - Questions related to Al's video (Battery, GPS & LORAN, Anchoring, Outboard mount, Camping rain-cover, Mosquito net, Heater)
- 1305.1 General Discussion - Lake lift off the water(Floating dock, Dissimilar metal corrosion)
- 1306.1 General Discussion - Stab AD (Reissue)
- 1307.1 Fly-in Notices - Fun event for western Lake drivers (Lake Mead)
- 1308.1 Operating Techniques - Normal Buc fuel pressure
- 1309.1 General Discussion - Salt water (1265.3, 1256.5, Flying Australia to Fiji)
- 1310.1 General Discussion - Steel vs aluminum
- 1311.1 Destinations - Illinois to Orlando (Info request)
- 1312.1 General Discussion - Chalks amphibian goes down (Mallard)
- 1313.1 General Discussion - Merry Christmas (Poem)
- 1314.1 Club Information - Fantasy of Flight
- 1315.1 Club Information - Wing spar fatigue photos (Chalks accident, 1312.1)
- 1316.1 Operating Techniques - Pop quiz - crosswinds
- 1317.1 Operating Techniques - Turbo charger operation (Link)
- 1318.1 Fly-in Notices - Lake-a-Thon - Getting there
- 1319.1 General Discussion - Unusual Lake activities (Water skiing, Snow landing, Solar charger, Lake A/C in Iraq, Wet Bottom Gang)
- 1320.1 Parts & Repair - Loss of manifold pressure (Gauge, Troubleshooting, Drains)
- 1321.1 General Discussion - Quebec hunting (Links, Lodges, Regulations, Seaplane bases)
- JAN 2006**
- 1322.1 Operating Techniques - Water loop crash (Goose, movie clip)
- 1323.1 General Discussion - Lycoming cam shaft failure (Wood chips, Cessna 177RG)
- 1324.1 General Discussion - General Discussion (Hartzell hub, Prop SB, possible AD)
- 1325.1 General Discussion - Help -need to contact member (Glen Carlson)
- 1326.1 Club Information - Member died (Murry Carslake)
- 1327.1 General Discussion - TAF diesel on a Lake?
- 1328.1 Does not exist
- 1329.1 Parts & Repair - Lycoming SB 566 expanded 11-30-2005 (Crankshaft)

- 1330.1 Operating Techniques - Take-offs at high altitudes**
(Procedure, Reduced MP, Mountain routes, Ridge lift)
- 1331.1 Operating Techniques - Mixture control** (Irregular control)
- 1332.1 General Discussion - Fuel pressure gauge** (Needle vibrating, Air leak)
- 1333.1 General Discussion - Unusual activities** (Aerobatics?)
- 1334.1 Parts & Repair - Main gear question** (O-rings, Spacers, Strut servicing)
- 1335.1 Parts & Repair - Air Pressure - struts** (Strut pumps, Air bottle)
- 1336.1 Destinations - Winter vacation** (Colorado, Arizona)
- 1337.1 General Discussion - AD 2005-26-10** (ECI parallel-valve cylinders)
- 1338.1 Parts & Repair - Main landing gear alignment**
- 1339.1 Destinations - Ontario fishing** (Camping fees, Saskatchewan)
- 1340.1 Parts & Repair - Hartzell hub issue** (Eddy current inspection at Lake-a-Thon)
- 1341.1 Parts & Repair - Horizontal Stabilizer fittings** (Factory fittings for sale)
- 1342.1 General Discussion - Heading to Mexico**
- 1343.1 Club Information - Lake-a-Thon** (Dates?)
- 1344.1 Parts & Repair - Anti-corrosion products & application**
(LPS3, ACF50, CorrosionX, Pressure applicator)
- 1345.1 Parts & Repair - Danger - Gasoline smell = explosion** (Fuel fittings, O-rings)
- 1346.1 Club Information - Lake Flyers flight reaction test** (Game)
- 1347.1 Club Information - Ensure your aircraft registration is current** (Link)
- 1348.1 General Discussion - Glenn H. Curtiss Museum**
- 1349.1 Does not exist
- 1350.1 General Discussion - Alternator trouble N1069L** (Over voltage, Spike, Relay, Diode)
- 1351.1 Parts & Repair - Power supply for strobe light**
- 1352.1 General Discussion - Flight tracking** (Link)
- 1353.1 General Discussion - Lake pre-purchase in New England**
- 1354.1 General Discussion - Lakeathon room**
- 1355.1 Parts & Repair - Help! Trim issue** (Clogged restrictors, Orifice size)
- 1356.1 For Sale & Wanted Ads - Need a prop** (For 180)
- 1357.1 Club Information - Weekend weather for Lakeathon**
- 1358.1 Club Information - Fly-out lunch at Lake-A-Thon** (Magnetos for 270)
- 1359.1 General Discussion - In need of insurance refresher flight** (At Lakeathon)
- 1360.1 Operating Techniques - Heater operation** (Fuel pressure, Fuel pump)
- 1361.1 Parts & Repair - Looking for armrest**
- 1362.1 Parts & Repair - Aux fuel tanks and pumps**
- 1363.1 Club Information - Weather forecast - Lakeflyers** (For Lakeathon)
- 1364.1 Club Information - Pete Hartmann made it to Florida**
- 1365.1 Club Information - Weather alert - Lakeflyers seminar**
- 1366.1 General Discussion - Failed engine cowling door latch**
- 1367.1 For Sale & Wanted Ads - Looking** (For a Buccaneer)
- 1368.1 Club Information - Photos of all Lakeflyers** (Link)
- 1369.1 For Sale & Wanted Ads - Hurricane-damaged Lake for sale** (1968 180)
- 1370.1 Parts & Repair - Pilot's-side door air vent**
- 1371.1 Club Information - Many thanks Marc, Jill, et all**
- 1372.1 General Discussion - New member buys Lake** (Financing, Insurance)
- 1373.1 General Discussion - Go-Jump-in-a- Lake Ts, Totes, Sweatshirts**

- 1374.1 General Discussion - Engine position (Shims)
- 1375.1 Parts & Repair - MT prop
- 1376.1 Parts & Repair -ASL Camguard (Oil additive)
- 1377.1 General Discussion - Aero Club Como (Link to article on Italian Renegade)
- 1378.1 General Discussion - Lake in CA (Also Lk Powell & Lk Mead)
- 1379.1 Operating Techniques - Helpful hints (Mistakes, Hazards)
- 1380.1 Parts & Repair - Buccaneer tachometer (EI, Horizon, JPI, Analyzer, Fuel flow)
- 1381.1 Club Information - Your photos, please (For Frappr site)
- 1382.1 Parts & Repair - Landing lights (High intensity, Two wings, Old-style part number)
- 1383.1 Parts & Repair - Hartzell hub issues 2
- 1384.1 Operating Techniques - IFR ops / Non-precision approaches
(Garmin 396, Anywheremap system)
- 1385.1 Operating Techniques - Water landing practice
(Not really- T-6 formation skimming the water)
- 1386.1 Operating Techniques - Cruising altitudes
(Power management, Leaning, “ Fearless Freddie”)
- 1387.1 General Discussion - Garmin 396 in Canada (No weather coverage, 296)
- 1388.1 Parts & Repair -Cylinder head cowling (Baffle wires)
- 1389.1 Parts & Repair - Turbo failure? (Broken air-box weld, Hose clamp)
- 1390.1 Parts & Repair - Roller tappets (Initial report)
- 1391.1 Operating Techniques - Portable fuel containers (Ferry flights, Wing tanks, Copeland floats)
- 1392.1 General Discussion - GPS satellite outages
- 1393.1 General Discussion - Alaska
- 1394.1 General Discussion - Trolling motors (Gas vs electric, Links)
- 1395.1 Destinations - Destination websites (Links)
- 1396.1 Parts & Repair - Elevator trim play
(Taper pin, Bolt access, Bendix vs Slick mags, Starter kick-back, Single magneto starting)
- 1397.1 General Discussion - Lake CD or Video tape (1112, 1135)
- 1398.1 Destinations - Stop by and visit (Yelm, Washington)
- 1399.1 Parts & Repair - Landing lights (Modification paperwork)
- 1400.1 General Discussion - Solar battery chargers/maintainers (Links, Flexcharge)
- 1401.1 General Discussion - Oil pressure (Fluctuations)
- 1402.1 Parts & Repair - Shimmy dampener
- 1403.1 General Discussion - Historical interest (Book: *Canadian Bush Pilot*, C-1)
- 1404.1 General Discussion - Grand Marais
- 1405.1 Parts & Repair - HID light papers from Pete (High intensity)
- 1406.1 General Discussion - Grand Marais (And Otsego)
- 1407.1 Parts & Repair - How to unsnap bladder?
- 1408.1 Parts & Repair - Crankshaft AD (Link)
- 1409.1 Fly-in Notices - Otsego Lake goes wireless
- 1410.1 Parts & Repair - Buc prop spinner (Looking for one)
- 1411.1 General Discussion - Paul Seehafer (For SPA post)
- 1412.1 General Discussion - Garmin 396 satellite antenna (Mounting, XM, NoCanadian)
- 1413.1 Club Information - Lake Reedy FLA lakefront home for sale
- 1414.1 Operating Techniques - PFD's (Warning about inflator failure, Spare Air, Egress)
- 1415.1 General Discussion - Wet Runway—the video (T-6 formation skimming the water)

- 1416.1 General Discussion - 270 manifold pressure (Turbo operation, Adjustment)
- 1417.1 Parts & Repair - Trim tab indicator (Inoperative, 1966 180, Cable)
- 1418.1 Club Information - LSA Mermaid (Light-Sport planes, Gannet)
- 1419.1 Parts & Repair - Pitot heat help
- 1420.1 Club Information - JPI or EI (Engine monitors)
- 1421.1 Parts & Repair - Broken valve spring
- 1422.1 Insurance - Insurance quote
- 1423.1 General Discussion - Free LORAN to a good home
- 1424.1 For Sale & Wanted Ads - Sweet aircraft (1967 LA4-180, sale)
- 1425.1 Parts & Repair - Horizontal stab AD (Parts info request)
- 1426.1 General Discussion - Factory support
- 1427.1 For Sale & Wanted Ads - Looking (Bought one)
- 1428.1 Destinations - Illinois River
- 1429.1 Parts & Repair - How to fix compass? (Adjustment procedure, Link, GPS, DG)
- 1430.1 General Discussion - Red-5 (Humorous radio exchange)
- 1431.1 Parts & Repair - Stab rivet issue (Installing H-stab kit)
- 1432.1 General Discussion - Inflatable boats (Pumps, Weight, Fishing)
- 1433.1 General Discussion - Lakeathon 2007 & Sun'n'fun (Change Lakeathon to April?)
- 1434.1 Fly-in Notices - Otsego Lake Splash-In info
- 1435.1 General Discussion - New Lake owner with questions
(Docking, Auto bilge-pump, Water level, Dock pictures, 881, 940)
- 1436.1 Destinations - Lake destinations in Frappr
- 1437.1 Fly-in Notices - When do you think Lakeathon should be held? (Poll)
- 1438.1 General Discussion - Trip to Michigan (Canadian overflight, Customs)
- 1439.1 General Discussion - Video of wheels-down water landing (266.6, Floatplane 1274.1)
- 1440.1 Parts & Repair - Hartzell hub crack (Replacement discount)
- 1441.1 Parts & Repair - Jacks/Jack stands
- 1442.1 Operating Techniques - Vapor lock (Hot starts)
- 1443.1 General Discussion - A virgin's view (Link: First-ride experience)
- 1444.1 General Discussion - What is a Lake worth? (Pre-purchase considerations)
- 1445.1 For Sale & Wanted Ads - LA4-200 for sale
- 1446.1 General Discussion - MT prop (Performance report, Renegade vs -200)
- 1447.1 Club Information - Derelict Lake aircraft (Near India. Current owner)
- 1448.1 Parts & Repair - Wheel - grease displacement (Foam inserts. Grease types)
- 1449.1 Parts & Repair - Horiz. -Vertical stab issue (Fairings & seals for H-stab)
- 1450.1 General Discussion - Aux fuel flow rate (Flow indicators)
- 1451.1 Parts & Repair - Tail AD (Hours to install)
- 1452.1 Wing A.D. - Time to complete AD (Unanswered question)
- 1453.1 Parts & Repair - Hydraulic hose replacement
- 1454.1 General Discussion -Pre-flight thoughts (Tips on drain plugs)
- 1455.1 Club Information - Great picture (Aero Club Como Renegade)
- 1456.1 For Sale & Wanted Ads - Heater (Unanswered question)
- 1457.1 General Discussion - Bilge pump (Locations, Main & aft hull,
Auto & hand pumps, Leak detection)
- 1458.1 Parts & Repair - Landing light (HID installation, Dual-wing)
- 1459.1 General Discussion - New E-mail address for Hartmann

- 1460.1 **Parts & Repair - Problem with S-Tec autopilot** (S-Tec 50/55X, Trim technique)
- 1461.1 **General Discussion - Trim lever** (In-flight break, Broken springs)
- 1462.1 **General Discussion - LA4-200 incident** (Water loop & sinking. Nanaimo BC. No injuries)
- 1463.1 **General Discussion - Lake camping**
- 1464.1 **Operating Techniques - Gear-up light** (Incomplete retraction, Trailing-link lubrication)
- 1465.1 **General Discussion - Dead-bug removal** (Bug Stuff, RejeX, Dryer sheets, Aerowash)
- 1466.1 **Parts & Repair - Oil change fun** (Suction pumping the sump & filter, 'Kneeling')
- 1467.1 **Parts & Repair - Hatch locking bars** (Door springs)
- 1468.1 **Operating Techniques - Water take-offs: Elevation above 4000 ft** (Turbo install)
- 1469.1 **Fly-in Notices - Otsego Lake splash-in "Last call"**
- 1470.1 **General Discussion - Engine oil spray** (Leak sources, Air/oil separator)

June 2006

- 1471.1 **Club Information - Pete Hartmann, come back!**
- 1472.1 **For Sale & Wanted Ads - Hard to find Lake book on Ebay**
- 1473.1 **Parts & Repair - Grease** (Colors, Kendall L-427)
- 1474.1 **Club Information - Required reading: 'Go to Hull'** (Link for download - SPA members)
- 1475.1 **General Discussion - Initial engine start-up** (Transient 'glitch', Aux pump)
- 1476.1 **Operating Techniques - Nose gear problem** (Retraction failure, Causes, Restrictor location)
- 1477.1 **General Discussion - New member/floating ramp**
- 1478.1 **Destinations - Pittsburgh area rivers** (Wire hazards)
- 1479.1 Does not exist
- 1480.1 **Insurance - Commercial insurance** (Trouble finding, Instructor experience, Training)
- 1481.1 **Parts & Repair - Looking for rubber nose bumper**
- 1482.1 **Parts & Repair - Installing VG's** (Adhesives, Flap VG's -vs -wing clearance issues)
- 1483.1 **General Discussion - Cellular phone interface** (Intercoms, ANR noise cancelling headsets)
- 1484.1 **Operating Techniques - Post-flight to save camshafts?** (Leave dipstick ajar)
- 1485.1 **General Discussion - MT prop** (User report)
- 1486.1 **Operating Techniques - Maximizing climb rate on a 200**
(Hi-altitude, Partial flap, Power settings)
- 1487.1 **For Sale & Wanted Ads - Wing covers for sale**
- 1488.1 **For Sale & Wanted Ads - Rare 94 acre Hudson River island**
- 1489.1 **For Sale & Wanted Ads - Factory tail fittings** (H-Stab, Sale)
- 1490.1 **General Discussion - Oil temp gauge** (Strange readings, Ground, Wiring)
- 1491.1 **Operating Techniques - Boost pump safety issue**
(Engine stoppage, High altitude, Boost pump, AirMaze filter, Engine failure accident)
- 1492.1 **General Discussion - Aircraft modifications** (Interior, Armrests)
- 1493.1 **Parts & Repair - Laser magneto** (Questions)
- 1494.1 **Operating Techniques - Dumping flaps on landing** (Debate)
- 1495.1 **General Discussion - Buying: What to look for / Midwest shops?**
- 1496.1 **General Discussion - Bat wings: pro and con?** (Comparison with VG's)
- 1497.1 **For Sale & Wanted Ads - 1967 Buccaneer for sale** (LA4-180)
- 1498.1 **General Discussion - Off-airport IFR clearance** (Requesting)
- 1499.1 **General Discussion - Zinc** (Post-saltwater care, Salt Off)
- 1500.1 **Parts & Repair - Aux fuel tank leaks**
- 1501.1 **General Discussion - Starter solenoid**(Intermittent actuation, Relay, Cole Hersee 24143)
- 1502.1 **General Discussion - Flight planning** (Link to planning site)

- 1503.1 **Parts & Repair - Right front cylinder** (Removal)
- 1504.1 **General Discussion - Rental costs for a Buc**
- 1505.1 **Parts & Repair - Prop bolt torque**
- 1506.1 **General Discussion - Garmin 396 GPS antenna location** (XM, Airgizmos link)
- 1507.1 **Fly-in Notices - Lakes at Oshkosh**
- 1508.1 **General Discussion - Engine angle and oil level** (Usage)
- 1509.1 **Parts & Repair - Floor boards** (Replacing. Cargo box)
- 1510.1 **Operating Techniques - Low oil pressure - land out** (Offshore landing, Regulator spring & ball)
- 1511.1 **Operating Techniques - Garmin 396**(AnywhereMap, XM, Lowrance 2000C, RAM mount)
- 1512.1 **Fly-in Notices - Stillwater splash**
- 1513.1 **General Discussion - Regional Lakeathons?** (Fly-ins)
- 1514.1 **General Discussion - Stillwater Fly-in**
- 1515.1 **General Discussion - Control locks** (Nelson Aileron-Lock)
- 1516.1 **General Discussion - T270 engine sputter** (Water, Turbo hose)
- 1517.1 **Parts & Repair - Brake help!** (LA4 master cylinder, Linkage)
- 1518.1 **General Discussion - 250 cylinder head temperatures**
- 1519.1 **General Discussion - Oshkosh - Cheap avgas in Indiana**
- 1520.1 **Parts & Repair - New panel question** (Replacement)
- 1521.1 **Parts & Repair - Landing mat sections**
- 1522.1 **General Discussion - Electrical thoughts**
(Short circuits, Aux power connector, Regulator, Over voltage, Connections)
- 1523.1 **General Discussion - Weight and Balance - One more time**
- 1524.1 **Parts & Repair - New engine - too good to be true?** (AES V-6, Innodyne turboprop)
- 1525.1 **General Discussion - 200 cylinder head temps** (Spark plug thermocouples)
- 1526.1 **General Discussion - Crosswind landings**
- 1527.1 **General Discussion - Aviation Consumer** (Upcoming article)
- 1528.1 **Club Information - A Lake Flyer suffers a loss** (McRoberts)
- 1529.1 **Parts & Repair - Hull strakes** (Want)
- 1530.1 Does not exist
- 1531.1 **General Discussion - Control locks** (Continuation of 1515)
- 1532.1 **General Discussion - Sometimes 25 miles are not enough** (Thunderstorm. Hung nose gear)
- 1533.1 **General Discussion - Fuel pressure fluctuation** (Under-panel leak. Remote-sender gauges)
- 1534.1 **General Discussion - I need some autopilot information** (STEC System 30, Century 2000)
- 1535.1 **General Discussion - Central Florida Lakes** (Looking for suggestions)
- 1536.1 **Parts & Repair - Old black hydraulic pump**
- 1537.1 **Club Information - Lake autopilots** (Brittain B5C, making it work)
- 1538.1 **General Discussion - Other flying boats** (Seamax, Gannet, Seawind)
- 1539.1 **Parts & Repair - Gerdes brake woes** (Linings crack on install, Rivets)
- 1540.1 Does not exist
- 1541.1 **Parts & Repair - LA-4 wingtips** (Need)
- 1542.1 **Parts & Repair - Fuel system maintenance tips review**
- 1543.1 **Operating Techniques - Minimizing wear on engine startup** (After extended downtime)
- 1544.1 **For Sale & Wanted Ads - Wanted: Book, 'Go to Hull' by Steve Reep**
- 1545.1 **General Discussion - Boater arrested for interfering with amphib**
- 1546.1 **General Discussion - Wind sock height** (Supports)
- 1547.1 **Fly-in Notices - 2007 Lake-a-thon is when?** (April 13-16)

- 1548.1 Parts & Repair - Looking for (Accessories)
- 1549.1 Fly-in Notices - Killarney Fly-In (Border crossing, Customs)
- 1550.1 General Discussion - Interesting trade (Air time: Lake for AN-2)
- 1551.1 Club Information - Lake Central fittings (H-stab AD, Inspection revision)
- 1552.1 General Discussion - Getting on the step (Not really - jet runs out of runway)
- 1553.1 General Discussion - Tows and tugs for aircraft (Airtug, Powertow 40EZ,)
- 1554.1 General Discussion - Prop AD (Eddy current inspection, MT prop performance vs Hartzell)
- 1555.1 Destinations - Pictures from Killarney Fly-In (Link)
- 1556.1 For Sale & Wanted Ads - For sale: Winter covers for LA-2/200
- 1557.1 Fly-in Notices - Flying from Seattle area to Lakeathon? (Any interest?)
- 1558.1 Fly-in Notices -Clear Lake Splash-In
- 1559.1 General Discussion - Posting pictures (Procedure, DC-3 wind vane at Whitehorse)
- 1560.1 General Discussion - Jetfloat dock (Wing root-to-waterline distance)
- 1561.1 General Discussion - Boat speed limit proposal - help! (SPA)
- 1562.1 Destinations - Bluegrass Splash-In, Florence, Ala.
- 1563.1 General Discussion - Lake Numbers?
- 1564.1 For Sale & Wanted Ads - Hartzell propeller blades (Sell, for Lake LA4-200)
- 1565.1 General Discussion - Lake embroidery on clothing source (Link)
- 1566.1 Parts & Repair - Prop inspection (Hub AD check, Removal necessary?)
- 1567 Does not exist
- 1568.1 Parts & Repair - Need a good paint shop
- 1569.1 General Discussion - Suggestions: Seaplane-friendly retirement (Looking for locations)
- 1570.1 Parts & Repair - Nose wheel and floorboards (Tire recommendation?)
- 1571 Does not exist
- 1572.1 Destinations - Stillwater (Picture and picture size)
- 1573.1 Parts & Repair - Prop comparison chart
- 1574.1 Parts & Repair - Eddy current test (Hartzell AD)
- 1575.1 Destinations - A Lake in Rio (Link to video clip)
- 1576.1 Parts & Repair - Landing gear (Intermittent gear-up light, Oil "blow-out", Jacks)
- 1577.1 Parts & Repair - 180 #379 parts (LA4-180 parts plane)
- 1578.1 For Sale & Wanted Ads - Books, mags, parts manuals (Publications for sale)
- 1579.1 Parts & Repair - Arrgh! Hydraulic woes: (Troubleshooting link,
Trim handle binding, Hand pump, Accumulator charge, Bad starter, Hand-propping)
- 1580.1 Fly-in Notices -Florida splash-in. Sat, Sept 30
- 1581.1 Operating Techniques -Gear down part way at shore
- 1582.1 General Discussion - Lake accident (Engine stoppage, bladder & cavity vents, see 1600.23)
- 1583.1 General Discussion - Low-level Lake flying Long Lake NY
- 1584.1 For Sale & Wanted Ads - Radios wanted
- 1585.1 Parts & Repair - Upgrades (Turbo. Fuel sponsons)
- 1586.1 General Discussion - Eby slough near Everett. Wa (Homebuilt amphibian accident)
- 1587.1 General Discussion - Fuel system design (Why fuselage tank?)
- 1588.1 Fly-in Notices -Not a fly-in: Movie 16R in Chicago
- 1589.1 General Discussion - Lake owners map (Frappr site)
- 1590.1 Parts & Repair - Hydraulic pump repair/replace (Repair kit, VG's, Bounce)
- 1591.1 Parts & Repair - General maint. parts (Need Brackett filter, Sharc 7 ELT battery)
- 1592.1 Fly-in Notices - Holiday Inn, Winterhaven

- 1593.1 Parts & Repair - Wheel grease** (To pack or not to pack, ANR headsets)
- 1594.1 For Sale & Wanted Ads - Lake Renegade 270T for sale**
- 1595.1 General Discussion - NYC Lidle crash graphic** (Into building. Flight path link)
- 1596.1 Club Information - Avweb picture** (Bob Copeland & plane. Hub AD Eddy current test)
- 1597.1 General Discussion - Pre-buy inspections!** (Info request)
- 1598.1 General Discussion - AOPA convention at Palm Springs**
- 1599.1 General Discussion - Pete's nose art**
- 1600.1 Parts & Repair - Need paint job** (Bad job-peeling paint. 1600.23, bladder & cavity vents.)
- 1601.1 General Discussion - Meeting suggestion** (Spatial disorientation DVD)
- 1602.1 General Discussion - Performance** (Turbo 200 or EP better?)
- 1603.1 General Discussion - Flight simulator, computer?** (Info request)
- 1604.1 Operating Techniques -Lin Zhi approach** (Link. Winding approach in Tibet)
- 1605.1 Parts & Repair - To defray the cost of #1** (Parts for sale)
- 1606.1 Parts & Repair - Light weight alternator**
(Plane Power, B&C , Starter, Hand propping, Battery, Trickle charge, Regulator)
- 1607 Does not exist
- 1608.1 Parts & Repair - Hartzell propeller blades** (For sale, Straight vs Q-tip)
- 1609.1 For Sale & Wanted Ads - Hartzell propeller blades** (Same as 1608.1)
- 1610.1 General Discussion - Punishment** (Legal stuff. 1600.34 continued)
- 1611.1 General Discussion - E-mail to Pete** (Legal stuff. 1600.34 continued)
- 1612.1 General Discussion - Great DVD** ([60° North at 500 feet](#))
- 1613.1 Insurance - Self insure** (Any interest as a group?)
- 1614.1 General Discussion - This is exciting.....** (Bureau of Reclamation lake closures)
- 1615.1 Parts & Repair - Strobe light**
- 1616.1 General Discussion -Fuel gauge problem**
- 1617.1 Parts & Repair - Neat stuff at AOPA convention**
- 1618.1 Fly-in Notices - Not too early to think about** (Lake Mead Grumman splash-in)
- 1619.1 Parts & Repair - Warning, Fuel selector checkout**
(Shut-off valve handle misalignment, Safety wire, Engine failure anecdote)
- 1620.1 Parts & Repair - Grease fitting** (Need tiny zerk)
- 1621.1 Parts & Repair - Pitot heater replacement** (Link)
- 1622 Does not exist
- 1623.1 Fly-in Notices - Pete, Don, Lake Mead**
- 1624.1 Parts & Repair - Rusty bottom-strut attachment** (Engine brace)
- 1625.1 Parts & Repair - Prop, need help** (Looking for AD information)
- 1626.1 For Sale & Wanted Ads - Hurricane damaged** (LA4 airframe for sale)
- 1627.1 General Discussion - Vortex generators** (Experience reports,
Takeoff distance, Slow speed control, No flap takeoff, Batwings, Root fairings,)
- 1628.1 Parts & Repair - MicroMesh** (Windscreen refinishing, Pledge)
- 1629.1 Operating Techniques -Hand propping** (Dead-battery priming)
- 1630.1 Destinations - Spring trips**
- 1631.1 Destinations - New Don Pedro res** (Visit report)
- 1632.1 Parts & Repair - Hydraulic trim valve problem** (Manufacturer, Part number)
- 1633.1 General Discussion -Salt water: To indulge or not to indulge?**
(Forced landing Damage report, Zinc chromate,)
- 1634.1 General Discussion -IFR avionics**

- 1635.1 Parts & Repair - Hartzell - Built on honor**(Experiences dealing with Hartzell, Spinner)
- 1636.1 General Discussion -Suggestion: LAFC website** (Also: Colonial/Lake history)
- 1637.1 For Sale & Wanted Ads - Buc for sale**
- 1638.1 Parts & Repair - Tow bar recommendations** (Links)
- 1639.1 Parts & Repair - Hull sealant?** (Removing ACF50/CorrosionX)
- 1640.1 For Sale & Wanted Ads - Propeller blades** (Posted earlier in 1608 & 1609)
- 1641.1 Destinations - Turbo Question** (High MP on takeoff)
- 1642.1 General Discussion -US Terminal Procedure publications** (Link to site for downloads)
- 1643.1 General Discussion -Another Lake alternative?** (Air Shark)
- 1644.1 For Sale & Wanted Ads - Insulated engine cover**
- 1645.1 Parts & Repair - Nose gear problem** (Actuator installation)
- 1646.1 Parts & Repair - Heater problem** (C&D thermostat)
- 1647.1 General Discussion -Killarney Fly-in 2007 dates?**
- 1648.1 General Discussion -Iridium spark plugs** (Gami injectors)
- 1649.1 For Sale & Wanted Ads - Trim-linkage covers**
- Jan 2007**
- 1650.1 General Discussion -New airplane** (Wing- in-ground-effect)
- 1651.1 Parts & Repair - Hartzell hub**
- 1652.1 General Discussion -Aircraft painting** (Report, Picture)
- 1653.1 Parts & Repair - Circuit breaker switch** (Request)
- 1654.1 Parts & Repair - Corrosion ?** (Main gear linkage, Silicon adhesive)
- 1655.1 Destinations - Calif Winter Flying** (Trip report)